

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 8 and 9

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

Original - Nathaniel Ford, under Contract #44 dated May 30, 1854 (DCSO records, Vol. 15 Pages 6480-81)

-----  
Set ¼ sec. post, from which  
A B.Oak 20" dia., bears S.78°E., 283 lks. dist.  
A B.Oak 12" dia., bears N.83°W., 341 lks. dist.

Douglas Co. Surveyors Office - James Byron, Deputy - Ray Irving, J. Fee, crew - Dec. 23, 1954 (Filed Dec. 10, 1957 from incomplete survey) - C.S. File 49/40

-----  
Both original BTs gone.  
Corner position determined by the extension of the section line from NW corner Sec. 9 through Interior L corner DLC 47 and half distance between NW and SW corners Sec. 9.  
I blaze and scribed 4 ft. W.Oak S.54½°E., 117.5 ft. ¼ S9 CS BT.  
I blaze and scribe 10" W.Oak N.26°E., 194.0 ft. ¼ S9 CS BT.

BLM resurvey by Robert J. Chappell, under Group #1616, surveyed June/Sept. 1991 (DCSO records Vol. 50 Pgs 18892-93)

-----  
Point for the ¼ sec. cor. of secs.8 and 9, at proportionate distance; there is no remaining evidence of the original corner.  
Set a stainless steel post, 28" long, 2½" dia., 34" in the ground, the top 6" below the surface of the ground with brass cap mkd.  
T29S R6W  
¼  
S 8 | S 9  
1991

from which  
A power pole, No. B17944, bears N.32°E., 219½ lks. dist. Deposit white "DEEP-1" magnetic marker at base of stainless steel post. The corner is located in a pasture.

From this point, a point reestablished as the ¼ sec. cor. of secs. 8 and 9 by Byron in 1954, recorded in DCSO records, corner renewal No. 134 (former record #), bears N.89°45'40"E., 0.700 chs. dist.; monumented with an iron post 1" dia., firmly set, flush with the ground, with brass cap mkd. DOUGLAS COUNTY OFFICE T29S R6W ¼S 8 9 1954. This point was established using erroneous control and is not utilized in this survey. From which a bearing tree mkd. by Byron:  
An Oak 47" dia., bears S.55°E., 178 lks. dist., with scribe marks S9 CS visible on opened blaze.

continued next page

TOWNSHIP 29 RANGE 06 POINT IDENTIFIER # 300540

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 8 and 9

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

Douglas County Surveyors Office - Randall Smith & Stephen  
Flause - Oct. 26, 1994 - C.S. 64/52-7

-----  
Found - 3½" dia. BLM Brass cap on 2½" od. iron pipe, 6"  
below ground (1991 BLM)  
DCSO BC/IP 1954 survey, bears N.89¾°E., 46.2' from  
BLM BC/IP (SEE NOTE)  
PPL power pole #B17944 bears N.32°E., 144.9' to  
outside edge of power pole facing corner, 145.5  
to center of power pole (1991 BLM)  
47" dia., W.Oak with a previously opened blaze bears  
S.65¼°E., 158.1' 1954 DCSO BT (Note BT to be cut  
in near future, stump will remain)  
1954 DCSO BC/IP bears N.89 3/4°E., 46.2' (agrees  
with 1991 BLM record)

NOTE - A 2½" dia brass cap on a 1½" o.d. iron pipe flush  
with ground. DCSO 1954 BC/IP was found being  
erroneously set, by 1991 BLM survey. We add the  
marks "void DCSO". (note property owner  
unwilling to have brass cap removed from iron  
pipe.

COUNTY SURVEYORS

T 29 S R 6 W

¼ | S

8 | 9

VOID DCSO

1954

OFFICE

South east BT form 1954 Ren agrees with rec., North  
east BT now gone.

New - 16" dia., W. Oak double blazed and scribed "¼ S9 CS  
BT" bears N.64½°E., 228.6'.

35" dia., Ash double blazed and scribed "¼ S8 CS BT"  
bears N44½°W., 308.5'.

Fd brass cap, Mark Heimburger, 2/2007 - M148-58

FD. BLM BC, PPL Pole, 2 BTs, & 1954 DCSO BC. SE Oak BT gone,  
1/2016 - C Sweeden M170-48 A&B