

TOWNSHIP 29 RANGE 06 POINT IDENTIFIER # 340300

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 21 and 28

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Original - Nathaniel Ford, under Contract #44 dated May 30, 1854 (DCSO records, Vol. 15 Page 6478)

Set ¼ sec. post, from which
A B.Oak 10" dia., bears N.33°W., 48 lks. dist.
A B.Oak 12" dia., bears S.48°E., 74 lks. dist.

J.W. Cole, County Surveyor - For: Rice Bros. - Wit: M.B. Hawkins; Tog Rice - March 1924 - Vol. 3 Pg. 183; Field Book 90 Pg. 46 (and "old" corner book, pg. 132)

I could find no trace of original corner. I renewed this corner on true section line one half way between section corners. I set an Iron pipe 1" x 36", 24" in the ground, from which
A Fir 12" dia., bears N.12°W., 11.0 ft.
Laurel 36" dia., S.29°30'W., 36.8 ft.

Douglas Co. Surveyors Office - James Byron, Deputy - Dale McFarland; John Powell, crew - April 1962 - C.S. 49/139-39

Found - 1" I.P. at corner and 2 ft. South of E-W fence.
36" Laurel S.29½°W., 36.8 ft. shows good scribing.
Cole's 14" Fir N.12°W., 11.0 ft., now stump.
New BT - 9" R.Fir N.14°W., 40.8 ft. scribed ¼ S21 CS BT.

BLM Resurvey by Wayne L. Rogers and Bryan S. Seibold, Cadastral Surveyors, under Group #1517, surveyed April/Aug. 1990 - (DCSO records Vol. 50 Page(s) 10183)

The 1/4 sec. cor. reestablished by proportionate measurement and recorded by J. W. Cole, in 1924, perpetuated and recorded by Byron, 1962. There is no remaining evidence of the original corner; therefore, this position is accepted as the corner, monumented with an iron pipe, 1 in. diam., firmly set, projecting 12 ins. above ground, from which the remains of the bearing trees mkd. by Cole:

A madrone, 36 ins. diam., bears S. 30½° W., 55½ lks. dist., with healed double blaze.

A sawed fir stump, 23 ins. diam., bears N. 13½° W., 17½ lks. dist., no marks visible.

and the remains of a bearing tree mkd. by Byron

A sawed fir stump, 12 ins. diam., bears N. 15½° W., 61½ lks. dist., no marks visible.

At the corner point

Set a stainless steel post, 28 ins. long, 2½ ins. diam., 23 ins. in the ground, with brass cap mkd.

(Cont. Next Page)

TOWNSHIP 29 RANGE 06 POINT IDENTIFIER # 340300

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 21 and 28

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

<p>T 29 S R 6 W ¼ $\frac{S\ 21}{S\ 28}$ 1990</p> <p>from which a new bearing tree A fir, 10 ins. diam., bears N. 36½° W., 49 lks. dist., mkd. 1/4 S21 BT. Deposit the iron pipe alongside the stainless steel post.</p>
<p>Found OK by K. DeGroot, May 2001 - 2001-0043</p>
<p>BLM dependent resurvey by Jeffrey O. Covington, Cadastral Surveyor, under Group No. 2940, surveyed June/Sept. 2019- (DCSO records Vol. 59 Page(s) 24016)</p> <p>-----</p> <p>The ¼ sec. cor. of secs. 21 and 28, reported by Rogers and Seibold in 1990, monumented with a stainless steel post, 2½" dia., firmly set, projecting 6" above ground, (alongside of which is an iron pipe, 1¼" dia., firmly set, projecting 14" above ground) with a brass cap (properly) mkd. from which the remains of the bearing trees reported by Rogers and Seibold</p> <ul style="list-style-type: none">A madrone, 36" dia., bears S.30½°W., 36.6 ft., with a healed double blaze.A fir, 16" dia., bears N.36½°W., 32.3 ft., with a healed blaze.A decayed fir stump, 12" dia., bears N.15½°W., 40.6 ft., no marks visible.A decayed fir stump, 22" dia., bears N.13½°W., 11.6 ft., with 2 healed blaze. <p>NAD 1983 (2011) Latitude: 43°01'40.14" N. Longitude: 123°24'52.02" W.</p>
<p>2</p>