

PRIMARY CORNER DESCRIPTION Center 1/4 Cor. for Sec. 9

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

BLM survey by Robert J. Chappel, under Group #1616, surveyed June 24 - Sept. 16, 1991 (DCSO records Vol. 50 Page(s) 18908)

-----  
Point for the center ¼ sec. cor. of sec. 9, at intersection with the E. and W. center line.

Set stainless steel post, 28" long, 2½ dia., 24" in the ground, with brass cap mkd. T29S R6W

C¼ S 9  
1991

from which

A Fir 15" dia., bears N.47½°E., 61½ lks. dist. mkd. C¼ S9 BT.

A Fir 13" dia., bears S.17°W., 118 lks. dist., mkd. C¼ S9 BT.

Deposit a white "DEEP-1" magnetic marker at base of stainless steel post.

Fd. OK by Lang, Sept. 1996 - M 128-69

-----  
Greg Lang - 5/10/2005 - C.S. File 65/54-17 & M147-60

Found - BLM brass cap 2½" in diameter.

20" fir bears N.47½°E., 40.59'

21" fir bears S.17°W., 77.88'

Both have healed faces & are in good condition.

New - 12½" fir bears N.70°W., 52.76' scribed "C¼ S9 BT"

6" Fir bears S.12°E., 38.00' scribed "C¼ S9 BT"

Note - Corner is located at a fence junction with fences running North, West, & South. It lies on a NW slope, just northerly of a thicket of reproduction fir.