

TOWNSHIP 29 RANGE 06 POINT IDENTIFIER # 500140

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs 34 and 35

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Original - Nathaniel Ford, under Contract #44 dated May 30, 1854 (DCSO records, Vol. 15 Page 6468)

Set ¼ sec. post, from which
A Pine 30" dia., bears S.27°W., 52 lks. dist.
A Cedar 20" dia., bears N.22°E., 35 lks. dist.

GLO survey by W.H. Byars, under contract # 152 survey dated June 3, 1871 (DCSO rec. Vol. 15 Page 6490)

Set ¼ sec. post, from which
A Laurel 6" dia., bears S.60°E., 39 lks. dist.
A W.Oak 16" dia., bears S.52°W., 44 lks. dist.

Douglas Co. Surveyors Office - James W. Byron, Deputy - Survey for: Dale Weekly - May 15, 1956 - C.S. File 47/93

Original BTs could not be found. Corner set by proportional measurement as per Byars survey of 1871.
Set an Iron pipe with brass cap at corner marked: ¼ S 34|S35 T29S R6W County Surveyors Office 1956.
Scribed two trees:
18" R.Fir N.48°30'E., 33.4 ft. mkd. ¼ S35 T29S R6W CS BT
14" R.Fir N.84°45'W., 27.0 ft. mkd. ¼ S34 T29S R6W CS BT
Corner is 42 ft. East of fence.

Survey by Howard Johnstone - For: Roseburg Lumber Co. - April 1978 - RM 3-12

At mid-point, Set 5/8" x 30" Iron rod and alum. cap.
BTs - 18" Fir S.43°W., 57.6 ft.
12" Fir N.54°E., 153.8 ft.
Iron Rod at improperly set ¼ corner bears N.6½°W., 30.1 ft.

Douglas Co. Surveyors Office - Rod Kimberling, Deputy - Steve Flause, crew - June 29, 1978 - C.S. file 60/11-25

Found - A 5/8" x 30" Iron rod with alum. cap set 1.0 ft. above ground mkd. 'T29S R6W 34 35 ¼ S LS 498 1978".
At location of improperly set ¼ corner, 5/8" I.R. bears N.6½°W., 30.1 ft. I attach an alum. cap marked "Douglas Co. Surveyor 1978".
An 18" Fir stump now bears N.22°E., 56.4 ft. (Rec. N.48½°E., 33.0 ft.) with scribing "BT" in bottom blaze.

(Cont. Next Page)

TOWNSHIP 29 RANGE 06 POINT IDENTIFIER # 500140

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 34 and 35

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

A 12" now 16" Fir is uprooted. Root hole bears N.45°W., 41.8 ft. (Rec. N.84 3/4°W., 27.0 ft.) with scribing "T29S R6W ¼ S34 CS BT" in a partly healed double blaze.

A 40" Fir snag 70 ft. high, bears N.84°E., 23.9 ft. (Rec. S.45 3/4°E., 39.6 ft.)

Set a 1" x 36" I.P. with brass cap set 4" above ground marked "Douglas County Surveyor". I set alum. cap under North edge of brass cap. Cap also marked T29S R6W ¼ S34 S35 1978. No new accessories. Corner is approx. 40 ft. East of fence.

Cadastral survey by Hans W. Thielsen and C. Albert White under Group #s 348 and 350. Surveyed, July 23, 1958 to Aug. 5, 1959 (DCSO records Vol. 30 Page(s) 12842)

The ¼ sec. cor. is monumented with an iron post, 1" dia., 10" above ground, firmly set, with DCSO brass cap. The Douglas County records show that this monument was set by Byron in 1956, at proportionate distance bet. the section corners.

At the corner point
Set an iron post, 28 ins. long, 2½ ins. dia., 20 ins. in the ground, with brass cap mkd:

	¼	
S 34	S 35	
T 29 S	R 6 W	
1958		

from which trees marked by Byron in 1956:

A sawed Fir stump 18" dia., bears N.48½°E., 50 lks. dist., mkd. BT at base.

A Fir 14" dia., bears N.84 3/4°W., 41 lks. dist. mkd. T29S R6W ¼ S34 CS BT.

and a new bearing tree:

A Fir 40" dia., bears S.45 3/4°E., 60 lks. dist., mkd. ¼ S35 BT.

Bury the County Surveyor's monument alongside the iron post.