

TOWNSHIP 29 RANGE 06 POINT IDENTIFIER # 540700

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 2; & 35, T28-6

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

Original - Elder and Gile, under Contract #31 dated April 7, 1853 (DCSO records, Vol. 14 Page 5699)

-----  
Set ¼ sec. post, from which  
A Y.Oak 9" dia., bears N.13½°E., 306 lks. dist.  
A Y.Oak 26" dia., bears S.72½°E., 296 lks. dist.

Arthur Boyer; N.E. Richardson; V. Phipps - March 10, 1937  
(Source for this record wording not found) See "old" corner book, Pg. 199

-----  
Conglomerate rock set from orig. Y.Oak stump hole which is S.72½°E., 396 lks. and from fallen dead Y.Oak N.13½°E., 306 lks.

New trees properly blazed and scribed:  
10" W.Oak N.8°E., 57.5 ft. marked CS BT.  
12" W.Oak S.34°45'E., 66 ft. mkd. CS BT.

-----  
Boyer; Richardson; Coon and Weigel - Dec. 1937 -  
C.S. File 30/44; Vol. 4 Page 42 & wording from old corner renewal #130 in T28-6 - - - -  
Found evidence of two orig. BTs for this cor. No knowledge of who set N.8"E and S.34°45'E BTs, which show ties. Rock is properly set. Drove 1½" Pipe beside rock, 46" in ground & 6" above ground near foot of hill at wedge of oak thicket.)

Fd. OK, July 20, 1984, DCSO, Randy Smith, C.S. File 62/18-22  
Fd. OK, OSHD, May 1986, C.S. File 63/9-8  
FD Ok by Mark Heimburger, May. 1996 - M 123-70  
Found OK by R.Quimby, July 1997 - Subd. Plat Vol. 19 Pg. 25  
Fd. ok by R. Brown, 6/2006-10/2007 - RM 4-15A&B