

TOWNSHIP 29 RANGE 06 POINT IDENTIFIER # 600240

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 25 and 26

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Original - Nathaniel Ford, under Contract #44 dated May 30, 1854 (DCSO records, Vol. 15 Page 6462)

Set ¼ sec. post, from which
A Red Fir 10" dia., bears S.83°W., 36 lks. dist.
A Cedar 30" dia., bears N.27°E., 43 lks. dist.

Frank Cain - Nov. 15, 1913 - Field Book 33 Page 18

A Maple 8" dia. marked C.S. ¼ S., from which
A Fir 30" di., mkd. C.S. ¼ S., S.25 BT bears N.55°E., 12 lks.
A Fir 16" dia., mkd. C.S. ¼ S., S26 bears N.89°W., 59 lks.

Survey by John H. Markham, Jr. - Wit: R.G. Boyd - For: Stomar Lumber Co. - Jan. 21, 1958 - C.S. File 42/325

Corner determined by Cain BTs:
24" Fir N.89°W., 39.0 ft.
42" Fir N.55°E., 8.0 ft.
At Corner point found 11" Maple and Set 1" x 30" Iron pipe, from which
14" W.Fir bears N.68°E., 75.0 ft. mkd. ¼ S25 BT.
14" Maple bears N.70°E., 108.0 ft. mkd. ¼ S25 BT.
Creek bears North, 160.0 ft.
Creek bears West, 157.0 ft.
Top of 60.0 ft. stone bears S.5°E., 180.0 ft.
Fence bears East and West from corner.

Douglas Co. Surveyors Office - Rod Kimberling, Deputy - M.W. Cline - Aug. 16, 1977 - C.S. File 59/38-16

Found - 1" x 30" Iron pipe 1.3 ft. South of an 8" now 13" Maple.
16" now 24" Fir stump set by Cain, 1913, uprooted with well healed blaze, opened and found scribing "S26". Stump hole bears N.89°W., 38.9 ft.
30" now 44" Fir with well healed blaze bears N.55°E., 7.9 ft.
14" now 16" W.Fir with well healed blaze bears N.68°E., 75.0 ft.
14" now 18" double trunked Maple with well healed blaze bears N.70°E., 108.0 ft.
A 1" Iron pipe bears S.35½°W., 10.0 ft. set by BLM 8" above ground.
Set 1" x 30" Iron pipe with brass cap at location of iron pipe set by Markham, 18" above ground in mound of stone 24" dia. to brass cap mkd: (Cont. Next Page)

TOWNSHIP 29 RANGE 06 POINT IDENTIFIER # 600240

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 25 and 26

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

<p>County Surveyors Office T 29 S R 6 W S 26 S 25 1/4 Cor 1977</p> <p>No new accessories.</p>
<p>DCSO-GIS Corner visitation - 8/17/2004 - Typed: 2/2/2011 - C.S. File 67/33-1</p> <p>-----</p> <p>Monument - BC/IP - 1.25" Comment - (needs) rehab</p>
<p>Douglas Co. Surveyors Office - Stephen J. Flause - Mike Koch - Garrett McGraw - 3/2/2011 - C.S. File 67/33-20</p> <p>-----</p> <p>Found - 1913 corner tree, a Maple 8" dia., now a 16" DBH maple with no blazes on marks evident and partially grown together with two smaller Maple trunks.</p> <p>At a point S.45°W., 0.8 ft. from the center root crown of the above fd 16" dia., Maple is a 2½" brass cap (properly mkd) on a 1½" ID iron pipe firmly set, protruding approx. 16" above a loose mound of a few stones. 1977</p> <p>1" iron pipe "SET BY BLM" mentioned in 1977 renewal is not found.</p> <p>No OBT found.</p> <p>Evidence of two 1913 BTs fd. These are referenced to the center root crown of the above mentioned Maple corner tree.</p> <p>A fir 30" dia., now a 6 ft. tall metal capped 44" DBH fir stump with a fully healed single blaze; bears N.55°E., 10.5 ft. (rec. N.55°E., 8.0 ft. is a good face measurement.)</p> <p>A fir 16" dia., now a down, out & rotted fir log (we do not look for marks) The root hole of which is reasonable for the N.89°W., BT.</p> <p>Evidence of two 1958 renewal trees fd. These are measured from BC mon.</p> <p>A 14" W.Fir now a 1½ ft. tall rotted 14" dia., fir stump with no remaining blaze evidence; bears N.68°E., 75.0 ft. (as per rec.)</p> <p>A 14" Maple, now a 19" DBH Big Leaf Maple with a fully healed double blaze bears N.70°E., 108.0 ft. (as per rec). Tree has additional limb like trunk DBH is from scribed trunk.</p> <p>continued next page</p>

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Ties to creek appear reasonable but the 60 ft. stone (rock out crop) is no longer observable due to forest growth.

A BT not of record with a BLM BT tag is fd. This is a 23" DBH D.Fir with a healed low blaze.

New - Previously noted unrecorded BT, A 23" DBH D.Fir to which we add an upper blaze scribed "¼ S25 CS" bears S.11°E., 23.6 ft

A 14" DBH D.Fir scribed "¼ S26 CS" "BT" on a double blaze; bears S.86°W., 35.9 ft.

Note - Monument is on steep NW slope. Terrain is mostly forested South and East from corner and is open and rocky North and West from corner.

Decl. 15¾°E.

BLM dependent resurvey by Jeffrey O. Covington, Cadastral Surveyor, under Group No. 2940, surveyed June/Sept. 2019- (DCSO records Vol. 59 Page(s) 24002)

The ¼ sec. cor. of secs. 25 and 26, reestablished by proportionate measurement by Cain, in 1913; perpetuated by Markham Jr., in 1958; subsequently perpetuated by the Douglas Co. Surveyor's Office, in 1977; further perpetuated by Smith, in 2011. There is no remaining evidence of the original cor. and this position is accepted as a careful and faithful reestablishment of the cor.; the cor. point is occupied by a maple, 24" dia., with a healed blaze on the west face, from which the remains of the bearing tree mkd. by Cain

A tin-capped fir stump, 34" dia., bears N.62°E., 9.3 ft., with a healed blaze.

and the remains of the bearing trees mkd. by Markham Jr.

A decayed fir stump, 16" dia., bears N.71°E., 80.8 ft., with a hollowed blaze.

A maple, 18" dia., bears N.73°E., 107.1 ft., with a healed blaze.

and a reference monument set by Douglas Co. Surveyor's Office

An iron post, 1¼" dia., firmly set, projecting 10" above ground, bears S.32°47'36"E., 1.00 ft., with a brass cap mkd. COUNTY SURVEYORS OFFICE T29S R6W S26 S25 ¼ COR 1977. At the request of the county surveyor, removed the marks on the brass cap and remarked the brass cap RM T29S R6W ¼ S25 1.00 FT TO COR BLM 2019 1977 and an arrow pointing to the cor.

and the bearing trees mkd. by Smith

A fir, 27" dia., bears S.11½°E., 23.6 ft., with a healed blaze.

A fir, 17" dia., bears S.85¼°W., 35.6 ft., with a healed blaze.

Continued next page

TOWNSHIP 29 RANGE 06 POINT IDENTIFIER # 600240

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 25 and 26

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

and new reference monuments
An iron rod, 30" long, 5/8" dia., driven 26" in the ground, for a reference monument, bears S.39°57'13"E., 14.89 ft., with aluminum cap mkd. RM1 T29S R6W ¼ S25 14.89 FT TO COR 2019 and an arrow pointing to the cor.
An iron rod, 30" long, 5/8" dia., driven 22" in the ground, for a reference monument, bears S.34°25'28"EW., (notes show EW) 15.89 ft., with aluminum cap mkd. RM2 T29S R6W ¼ S26 15.89 FT TO COR 2019 and an arrow pointing to the cor.
Add the marks S25 on the east face and ¼ S26 on the west face of the cor. tree, on the bark.
Corner is located alongside a fence cor., with wire fences extending N., E., and W.