

TOWNSHIP 29 RANGE 06 POINT IDENTIFIER # 600300

PRIMARY CORNER DESCRIPTION Sec. Cor. for 23, 24, 25 and 26

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Original - Nathaniel Ford, under Contract #44 dated May 30, 1854 (DCSO records, Vol. 15 Page 6462)

Set post, cor. of secs. 23, 24, 25 and 26, from which
A W.Oak 6" dia., bears S.21½°E., 27 lks. dist.
A Fir 30" dia., bears N.85½°E., 58 lks. dist.
A W.Oak 20" dia., bears N.42°W., 135 lks. dist.
A B.Oak 10" dia., bears S.23½°W., 68 lks. dist.

Survey by John H. Markham, Jr. Engineer- For:Wm. & George Vaughn - Dec. 29, 1950 and Jan. 14, 1951 - C.S. File 40/294

Determined by O.B.T., a 50" Fir bears N.85°E., 38.5 ft. Remark this O.B.T. "S24 BT".
A W.Oak slag 20" dia., bears N.42°W., 89.0 ft. O.B.T.
At Corner point, found Oak post and set 3/4" x 20" Iron pipe from which
A Fir stump 13" dia., bears N.20°W., 14.5 ft. mkd S23 BT.
A Fir 16" dia., bears S.30°W., 39.0 ft. mkd. S26 BT.

Douglas Co. Surveyors Office - James W. Byron, Deputy - Dale McFarland and John Powell, Crew - April 1962 - C.S. File 49/139-50

Found - 3/4" I.P., 6" under surface at corner.
50" now 50" Red Fir N.85°E., 38.5 ft. shows good bark scribing.
SW. and NW. BTs now stumps, show bark scribing.
Set Brass cap alongside Cor. I.P. mkd: County Surveyor Office
T 29 S R 6 W
S 23 | S 24
S 26 | S 25
1962

New BTs -12" Red Fir bears S.56°E., 32.0 ft. scribed S25 T29S R6W CS BT.
8" W.Oak bears N.59°W., 128.6 ft. scribed S23 CS BT.
20" Laurel bears S.17½°W., 74.7 ft. scribed S26 T29S R6W CS BT.

Douglas Co. Surveyors Office - John Powell, Frank Jones, W. Penley - July 1969 - C.S. File 49/139-123

Found - DCSO brass cap, properly marked in 1962.
50" D.Fir now stump, N.85°E., 38.5 ft. no scribe visible.
12" D.Fir now snag, S.56°E., 32.0 ft. scribe visible.

(Cont. Next Page)

TOWNSHIP 29 RANGE 06 POINT IDENTIFIER # 600300

PRIMARY CORNER DESCRIPTION Sec. Cor. for Secs. 23, 24, 25 and 26

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

<p>8" W.oak now cut down, N.59°W., 128.6 ft. 20" Laurel now pushed out, S.17½°W., 74.7 ft. scribe visible.</p> <p>New BTs -13" D.Fir N.3°E., 65.5 ft. mkd: T29S R6W S24 CS BT. 7" W.Oak N.43°E., 24.0 ft. mkd. T29S R6W S24 CS BT. 24" D.Fir S.76°E., 94.4 ft. mkd. T29S R6W S25 CS BT. 13" D.Fir S.20°W., 142.4 ft. mkd. T29S R6W S26 CS BT</p> <p>This corner is in fence corner, fences running approx. E.& S.</p>
<p>DCS0-GIS Corner visitation - 8/18/2004 - Typed: 2/2/2011 - C.S. File 67/33-1</p> <p>-----</p> <p>Monument - BC/IP - 1.25" Comment - (needs) rehab</p>
<p>Greg Lang - For: Roseburg Resources - March 2005 - M147-40 & C.S. File 65/54-16B</p> <p>-----</p> <p>Found - Douglas County Brass Cap Remains of original 30" Fir (now a 50" stump) still in existence; also found remains of two stumps by Markham in 1951; and remains of Red Fir by Byron in 1962 The remains of badly rotted NE stump & the SE stump covered with tin from the 1969 renewal 20" D.Fir bears S.14°W., 143.60' (S.20°W., 142.4' 1969) 12½" Oak bears N.41°E., 23.80' (N.43°E., 24' 1969)</p> <p>New - 6" D.Fir bears S.76°E. 23.6' scribed "T29SR6WS25 BT" 18" D.Fir bears N.71°W. 71.0' scribed "T29SR6WS23BT"</p> <p>Note - We set & measured to spikes in the base of all four standing BTs; bearings to the trees are based on Barne's 1974 survey line from this E 1/16th Cor to the SE corner of Section 23 (S88°34'32"E). Corner is located on an easterly slope and is about 100' westerly of Boomer Hill Rd.</p>
<p>BLM dependent resurvey by Jeffrey O. Covington, Cadastral Surveyor, under Group No. 2940, surveyed June/Sept. 2019- (DCS0 records Vol. 59 Page(s) 24003-4)</p> <p>-----</p> <p>The cor. of secs. 23, 24, 25, & 26, perpetuated by Markham Jr., in 1951; subsequently perpetuated by Byron, in 1962; further perpetuated by Byron in 1969; further perpetuated by Lang, in 2005; monumented with an iron post, 1" dia., projecting 14" above ground, with a brass cap (properly) mkd.</p> <p>Continued next page</p>

TOWNSHIP 29 RANGE 06 POINT IDENTIFIER # 600300

PRIMARY CORNER DESCRIPTION Sec. Cor. for 23, 24, 25 and 26

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

from which the remains of an original bearing tree
A decayed fir stump, 50" dia., bears N.85½°E., 38.3 ft.,
no marks visible.
and the remains of a bearing tree mkd. by Markham Jr.
A decayed fir stump, 24" dia., bears S.33½°W., 38.3 ft.,
with scribe marks S26 visible on bark.
and the remains of a bearing tree mkd. by Byron in 1962
A decayed fir snag, 12" dia., bears S.55¾°E., 31.4 ft.,
with a healed blaze.
and the bearing trees mkd. by Byron in 1969
An oak, 16" dia., bears N.44°E., 23.8 ft., with a healed
blaze.
A fir, 24" dia., bears S.13½°W., 143.6 ft., with a healed
blaze.
and the remains of the bearing trees mkd. by Lang
A fir, 14" dia., bears S.77¼°E., 23.6 ft., with a healed
blaze.
A roothole bears N.71¼°W., 68.5 ft., alongside of which is
a down fir, 22" dia., with a healed blaze.
and a new bearing tree
A fir, 7" dia., bears N.50¼°W., 29.3 ft., mkd. T29S R6W
S23 BT.
Corner is located alongside a dilapidated fence cor., with
wire fences extending E. and S.