

TOWNSHIP 29 RANGE 06 POINT IDENTIFIER # 700300

PRIMARY CORNER DESCRIPTION Sec Cor for 24 & 25; & 19 & 30, T29-5

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

Original - Nathaniel Ford, under Contract #44 dated May 30, 1854 (DCSO records, Vol. 15 Page 6421)

-----  
Set a post for cor. to secs. 19, 24, 25 and 30, from which  
A B.Oak 12" dia., bears N.10°W., 150 lks. dist.  
A W.Oak 15" dia., bears S.85°W., 175 lks. dist.  
A W.Oak 10" dia., bears N.70°E., 459 lks. dist.  
A Red Fir 15" dia., bears S.2°E., 208 lks. dist.

Douglas Co. Surveyors Office - James Byron, Co. Surveyor - John Powell and Crew - Feb. 1969 - C.S. File 54/79; M 37-20

-----  
Prorated section corner.  
Set Brass cap at cor. mkd: County Surveyors Office  
R T 29 S R  
6 S 24 | S 19 5  
W S 25 | S 30 W  
1969

New BTs -13" D.Fir S.40°W., 25.1 ft. mkd. T29S R6W S25 CS BT  
14" D.Fir N.43°W., 30.2 ft. mkd. T29S R6W S24 CS BT  
6" D.Fir S.56°E., 25.2 ft. mkd. S30 CS BT.  
No trees to the NE Quadrant.  
Fence corner running N. and W. bears N.15°W., 28.6 ft.

Douglas Co. Surveyors Office - Rod Kimberling, Deputy - P. Earle - June 14, 1977 - C.S. File 59/34-38

-----  
Found - 1969 DCSO brass cap properly marked, bears N.68°E., 17.4 ft. from orig. corner located from O.B.T.  
From Brass Cap:  
13" now 18" D.Fir bears S.40°W., 25.1 ft.  
14" now 22" D.Fir bears N.43°W., 30.2 ft.  
6" now 8" D.Fir bears S.56°E., 35.3 ft. (Rec. 25.2 ft.) BT tag said 35.2 ft.  
All BTs had double well healed blazes.  
From apparent original corner location:  
A D.Fir stump, 15" now 40" bears S.2°E., 137.3 ft. with previously opened single blaze. Found scribing "2" S30 BT.  
Reset Brass cap in orig. location stamped to now read:  
County Surveyor's Office  
R T 29 S R  
6 S 24 | S 19 5  
W S 25 | S 30 W  
1969  
Reset  
1977

(Cont. Next Page)

TOWNSHIP 29 RANGE 06 POINT IDENTIFIER # 700300

PRIMARY CORNER DESCRIPTION Sec Cor for 24 & 25; & 19 & 30, T29-5

|             |                   |
|-------------|-------------------|
| Alias _____ | Description _____ |
| Alias _____ | Description _____ |
| Alias _____ | Description _____ |
| Alias _____ | Description _____ |

Drove a 5/8" Iron rod with alum. cap at location where we removed brass cap. Alum. cap bears N.68°E., 17.4 ft. stamped "CS 1977". We used already scribed BTs which now face 5/8" I.R. as follows:

18" D.Fir bears S.0°30'W., 13.7 ft.

22" D.Fir bears N.9°W., 28.4 ft.

8" twin trunked D.Fir bears S.75°E., 47.9 ft.

All BTs have double well healed blaze.

A wire fence running W. and N. has corner which bears N.15°E., 35.0 ft. dist.

BLM dependent resurvey by Jeffrey O. Covington, Cadastral Surveyor, under Group No. 2940, surveyed June/Sept. 2019- (DCSO records Vol. 59 Page(s) 23996-7)

-----  
The cor. of secs. 19, 24, 25, and 30, perpetuated by Douglas County Surveyor's Office, in June of 1977; monumented with an iron post, 1" dia., firmly set, projecting 6" above ground, with a brass cap (properly) mkd.

from which the remains of an original bearing tree

A decayed fir stump, 40" dia., bears S.2°E., 137.3 ft., with scribe marks 2 30 BT visible on open blaze.

and the BTs mkd. by Byron, in 1969, & reused by Douglas Co. Surveyor's Office

A fir, 22" dia., bears S.73¼°E., 48.6 ft., with a healed blaze.

A fir, 27" dia., bears S.5°W., 14.2 ft., with a healed blaze.

A fir, 34" dia., bears N.4°W., 27.1 ft., with a healed blaze.

and a new bearing tree

A cedar, 13" dia., bears N.35°E., 41.9 ft., mkd. T29S R5W S19 BT.

From this cor., a point erroneously established as the cor. of secs. 19, 24, 25, and 30, by Byron, in 1969; perpetuated by Douglas Co. Surveyor's Office, in 1977. This point was established using improper control and was not utilized for control in this survey, bears N.70°21'56"E., 17.74 ft.; monumented with an iron rod, 5/8" dia., firmly set, projecting 4" above ground, in a collar of stone, with an aluminum cap mkd. DOUGLAS CO. SURVEYOR CS 1977; from which the bearing trees mkd. by Byron

A fir, 22" dia., bears S.56¼°E., 35.9 ft., with a healed blaze.

A fir, 27" dia., bears S.37½°W., 25.4 ft., with a healed blaze.

A fir, 34" dia., bears N.41¼°W., 28.1 ft., with a healed blaze.

Continued next page

TOWNSHIP 29 RANGE 06 POINT IDENTIFIER # 700300

PRIMARY CORNER DESCRIPTION Sec Cor for 24 & 25; & 19 & 30, T29-5

|             |                   |
|-------------|-------------------|
| Alias _____ | Description _____ |
| Alias _____ | Description _____ |
| Alias _____ | Description _____ |
| Alias _____ | Description _____ |

The 1969 iron post was reset by Douglas County Surveyor's Office in its original position and the erroneously established position was perpetuated with an iron rod.