

TOWNSHIP 29 RANGE 07 POINT IDENTIFIER # 038020

PRIMARY CORNER DESCRIPTION NW Cor. Byron DLC #38

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Original - Bowman and Burnett, under Contract dated Sept. 1855  
-----  
Set a Post, from which  
A W.Oak 8" dia., bears N.20°W., 154 lks.

F.C. Frear - Wit: P.D. Wolford; J.H. Wolford; N.E. Richardson - April 15, 1936 - C.S. File 23/30  
-----  
Found One old BT. Marked new trees and drove a 1" x 30" Iron bar for corner, from which  
A 12" Fir, S.56°45'E., 5.0 ft.  
A 12" Fir, N.83°00'W., 8.9 ft.  
A 36" Cedar, S.26°30'W., 18 ft.  
A 14" W.Oak, N.20°W., 101.6 ft.

Douglas Co. Surveyors Office - Ben B. Irving; James Byron; Ray Irving - Work done under order of County Court, in connection with Road survey, Co. Rd. #38 - Feb. 1954 - C.S. File 46/36  
-----  
Location identified from 3 BTs as set by Frear in 1936. Oak, N.20°W., destroyed. Corner destroyed.  
Set 1" x 36" Iron pipe with brass cap stamped "County Surveyors Office".

Douglas Co. Surveyors Office - James W. Byron - M. Godfrey; S. Bilow - Dec. 17, 1957 - C.S. File 49/139-1  
-----  
Found - I.P. with brass cap stamped "County Surveyors Office, 1954, N.W. Corner D.L.C. No. 38".  
14" Fir stump N.81°W., 9.5 ft., bark scribed "S NW C 38 BT" visible.  
Fir BT to SE is uprooted and down, cannot get accurate bearing or distance to it.  
Blaze and Scribe trees "N.W. Cl 38 CS BT":  
40" Incense Cedar, S.28°W., 20.0 ft.  
17" Incense Cedar, S.26°E., 47.9 ft.

Fd. OK, Victor McLind - Jan./Aug. 1972 - RM 2-35

Douglas Co. Surveyors Office - Randall W. Smith - Stephen J. Flause - 1/12/98 - C.S. File 64/79-2  
-----  
Found - 2½" dia., brass cap on a 1½" O.D. iron pipe, protrudes 5" above ground.  
Cont. next page

TOWNSHIP 29 RANGE 07 POINT IDENTIFIER # 038020

PRIMARY CORNER DESCRIPTION NW Cor Byron DLC #38

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

17" now 32" dia., I.Cedar with a fully healed single blaze, bears S.26°E., 47.9 ft. (Agrees with rec.) 1957

12" now 14" dia., 2 ft. high, rotted D.Fir stump with bark scribing visible "NW C38 BT" bears N.83°W., 9.5 ft. (Rec. per 1936 N.83°W., 8.9 ft. fits blaze) (Rec. 1957 N.81°W., 9.5 ft)

12" now 13" dia., 2 ft. high rotted and tipped out of position, D.Fir stump, no scribing visible is found near rec. position "S.56 3/4°E., 5.0 ft." 1936

36" now 47" dia., I.Cedar with flat bark, no bark scribing visible and a fully healed single blaze bears S.28°W., 20.0 ft. (Agrees with 1957 rec.) (S.26½°W., 18 ft. rec. from 1936, fits well as a blaze measurement per 1936 & 1957)

New BTs- 9" dia., D.Fir, double blazed and scribed "NW DLC 38 BT" bears S.83°E., 12.8 ft.

8" dia., D.Fir, double blazed and scribed "NW DLC 38 BT" bears N.36°W., 8.0 ft.

Fd. BC by Neil Hibbs, 5/2008 - M155-78