

PRIMARY CORNER DESCRIPTION Sec. Cor. for 16, 17, 20 and 21

Alias	Description
Alias	Description
Alias	Description
Alias	Description

Original - Nathaniel Ford, under Contract #44 dated May 30, 1854 (DCSO records, Vol. 15 Page 6536)

Set a post, cor. of secs.16, 17, 20 and 21, from which
 A Laurel 8" dia., bears S.10°E., 85 lks. dist.
 A Red Fir 10" dia., bears N.20°E., 68 lks. dist.
 A Laurel 4" dia., bears N.53°W., 23 lks. dist.
 A Laurel 8" dia., bears S.8°W., 50 lks. dist.

Douglas Co. Surveyors Office - Ben B. Irving, James W. Byron, Ray Irving - Work done for County Engineer, Rd. #38 - Feb. 1954 - C.S. File 46/36

Corner renewed from orig. BT, 42" Fir N.20°E., 44.9 ft. We cut out to old blaze and fund several scribe marks. We found 3" x 3" scribed yewood post, from which
 18" Fir stump scribed BTX N.44°W., 27.5 ft.
 18" Red Fir stump S.38°E., 8.8 ft. scribed S X.
 Bearing trees were scribed 30 to 40 years ago but were not recorded.
 Set 1" I.P. with brass cap mkd: 17, 16, 20, 21, County Surveyor's Office, T29S R7W 1954, from which
 Red Fir 10" dia., N.52°E., 1.0 ft. mkd. T29S R7W S16 CSBT
 Red Fir 10" dia., S.58°E., 18.7 ft. mkd. T29S R7W S21 CSBT
 Red Fir 10" dia., N.75°W., 14.6 ft. mkd. T29S R7W S17 CSBT
 Red Fir 8" dia., S.22°W., 25.8 ft. mkd. T29S R7W S20 CSBT

Douglas Co. Surveyors Office - James Byron, Deputy - March 22, 1957 - C.S. File 47/165

This corner was renewed in 1954 by County Surveyor. I find the NE BT uprooted and brass cap lying 50 ft. downhill. All other BTs uprooted except the NW BT which is still standing which I use to replace the brass cap.
 Blaze and scribe new BTs:
 16" R.Fir S.38°E., 62.0 ft. mkd. T29S R7W S21 CS BT.
 5" W.Fir N.24°W., 41.2 ft. mkd. S17 CS BT.

GLO resurvey by Hans W. Thielsen under Group #346, Surveyed, April/May 1957 - (DCSO records Vol. 28 Page(s) 12156-57)

Found cor. remonumented with an iron post, 1" dia., 10" above ground, firmly set, with brass cap marked:

COUNTY SURVEYORS OFFICE

T29S R7W
 17|16

 20|21
 1954

(Cont. Next Page)

PRIMARY CORNER DESCRIPTION Sec. Cor. for 16, 17, 20 and 21

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

from which
 A sawed Fir stump 42" dia., bears N.20°E., 63 lks. dist., with faint scribe marks visible on opened blaze. (An original bearing tree)
 A Fir 16" dia., bears S.39°E., 94 lks. dist., mkd. T29S R7W S21 CS BT. (1957 BT.)
 A Fir 10" dia., bears N.75°W., 22 lks. dist., mkd. T29S R7W S17 CS BT. (1957 BT.)
 A Fir 6" dia., bears N.24½°W., 63 lks. dist., mkd. T29S R7W S17 CS BT. (1954 BT.)
 This cor. was remonumented in 1954 from the original NE BT, and four new BTs were marked. All but the one listed above were subsequently uprooted during logging operations, and the I.P. was pulled up. The post was reset in 1957 by Byron, who also marked the additional trees listed above.
 At the cor. point
 Set an iron post, 3 ft. long, 2" dia., 28" in the ground, with brass cap marked:

T29S R7W	
S 17	S 16
S 21	S 20
1957	

 from which new bearing trees:
 A Fir 8" dia., bears N.72°E., 114 lks. dist., mkd. T29S R7W S16 BT.
 A Fir 17" dia., bears S.13°W., 190 lks. dist., mkd. T29S R7W S20 BT.
 Reset County Surveyor's monument alongside the iron post.

BLM resurvey by John M. Jelley under Group #346, Surveyed, Aug/Oct. 1966 - (DCSO records Vol. 34 Page(s) 14297-98)

 The Sec. cor., perpetuated and recorded by Byron, 1954, monumented with an I.P. 1" dia., firmly set, extending 8" above ground, with brass cap mkd: COUNTY SURVEYORS OFFICE T29S R7W 16 17 20 21 1954. Subsequently remonumented by Thielsen in 1957, with an iron post, 2" dia., firmly set, extending 8" above the ground, with brass cap mkd: T29S R7W S 17 S 16 S 20 S 21 1957, from which the remaining original bearing tree:
 A sawed Fir stump 42" dia., bears N.20°E., 68 lks. dist., with illegible scribe marks visible on opened blaze. and bearing trees mkd. by Byron in 1954:
 A down Fir 10" dia., bears N.52°E., 1½ lks. dist., with scribe marks T29S R7W S16 CS BT visible on unhealed double blaze.
 A Fir 13" dia., bears N.75°W., 22 lks. dist., with healed double blaze.
 (Cont. Next Page)

PRIMARY CORNER DESCRIPTION Sec. Cor. for 16, 17, 20 and 21

Alias	Description
Alias	Description
Alias	Description
Alias	Description

and bearing trees marked by Byron in 1957:
A down Fir 18" dia., bears S.38°E., 94 lks. dist., with healed double blaze.
A W.Fir 12" dia., bears N.24°W., 62 lks. dist., with healed double blaze.
from which new bearing trees:
A Fir 10" dia., bears N.38½°E., 119 lks. dist., mkd. T29S R7W S16 BT.
A Fir 10" dia., bears S.41½°E., 88 lks. dist., mkd. T29S R7W S21 BT.
A Fir 17" dia., bears S.88°W., 163 lks. dist., mkd. T29S R7W S20 BT.

Douglas Co. Surveyors Office - L.E. Monrean, Deputy - K. Cheney; P. Earle - Jan. 12, 1977 - C.S. File 59/29-9

Found - 1954 DCSO brass cap.
1957 U.S. GLO brass cap, properly marked.
An orig. 10" R.Fir now 42" sawed stump, bears N.20°E., 44.9 ft. No visible scribing on prev. opened blaze.

The SE, NW and SW orig. BTs not found.

Found per County, 1954:

- 10" R.Fir now a down 10" Fir bears N.52°E., 1 ft. partial scribing visible.
- 10" R.Fir now a 13" tipped out stump, bears S.58°E., 18.7 ft. No scribing visible.
- 10" R.Fir now a 13", bears N.75°W., 14.5 ft. with healed over double blaze.
- 8" R.Fir now a 9" tipped out stump, bears S.22°W., 25.8 ft. No visible scribing.

The two unrecorded BTs per 1954 notes, not found.

Found per County, 1957:

- 16" R.Fir now a 18" down Fir, bears S.38°E., 62 ft. with healed over double blaze.
- 5" W.Fir now 16", bears N.24°W., 41.2 ft. with healed double blaze.

Found per BLM, 1957:

- 10" Fir now 15" bears N.38½°E., 78.5 ft. Healed over blaze.
- 10" Fir now 13" bears S.41½°E., 58.1 ft. with healed blaze.
- 17" Fir now 21" bears S.88°W., 107.6 ft. with healed blaze.

Note: Found unrecorded 19" Fir stump bears N.19½°E., 23.2 ft. visible scribing "BT".

A fence corner bears N.77°E., 1 ft. Said fence runs easterly and southerly.

PRIMARY CORNER DESCRIPTION Sec. Cor. for 16, 17, 20 and 21

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Fd. OK, June 1992, Gregory Lang, M 115-30
 Fd. OK, April 1996 by K. Westersund - M 126-71
 Fd. Ok, Oct. 1998 by Gregory Crites - M 130-43

BLM dependent resurvey by Bryan S. Seibold, Cadastral Surveyor, and Robert Browning, Surveying Technician, under Group #1745, surveyed Aug. 1994 thru April. 1995 - (DCSO records Vol. 52 Page(s) 20073-4)

 From the cor. of secs. 16, 17, 20 & 21, monumented with an iron post, 2" diam., firmly set, projecting 7" above ground (with an iron post, 1½" diam., firmly set, projecting 6" above ground, with brass cap mkd. COUNTY SURVEYORS OFFICE T29S R7W S16 S17 S20 S21 1954, alongside), w/brass cap mkd.

T29S	R7W
S 17	S 16
S 20	S 21

1957

from which the remains of an original bearing tree
 A sawed fir stump, 46" diam., bears N.20°E., 68 lks., with fragmentary scribe marks visible on opened blaze.
 and a bearing tree mkd. by Ben B. Irving, Deputy County Surveyor, in 1954
 A fir, 16" diam., bears N.75°W., 22 lks., with healed double blaze.
 and the remains of bearing trees mkd. by James W. Byron, Deputy County Surveyor, in 1957
 A root hole bears S.38°E., 94 lks., with down 16" diam., trunk alongside, with no marks visible on opened blaze.
 A fir, 23" diam., bears N.24°W., 62 lks., with healed double blaze.
 and bearing trees mkd. by Jelley in 1957
 A fir, 19" diam., bears N.38½°E., 119 lks., with healed blaze.
 A fir, 19" diam., bears S.41½°E., 88 lks., with healed blaze.
 A fir, 30" diam., bears S.89°W., 163 lks., with healed blaze. (Record, S.88°W.)
 and the remains of bearing trees mkd. by person(s) unknown
 A sawed fir stump, 21" diam., bears N.19 3/4°E., 35 lks., with scribe marks BT visible on the bark.
 A sawed fir stump, 20" diam., bears N.19½°W., 78 lks., with scribe marks BT SX visible on opened blaze.
 The corner is located 2 lks. W. of a fence corner, with barbed wire fences extending S. and E.