

PRIMARY CORNER DESCRIPTION Sec. Cor. for 4, 5, 8 and 9

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Original - Nathaniel Ford, under Contract #44 dated May 30, 1854 (DCSO records, Vol. 15 Page 6538)

Set a post corner of secs. 4, 5, 8, and 9, from which
A B.Oak 24" dia., bears N.4°E., 600 lks. instead.
A B.Oak 28" dia., bears N.33°W., 630 lks. dist.
A mound made according to instructions.

Douglas Co. Surveyors Office - J.W. Cole; Fred Byron; Jesse Ware - June 15, 1916 - C.S. File 37/113 ("old" cor. bk. Pg. 133)

From stump of an Oak designated as a witness tree by Fred Byron, run S.4°W., 600 lks. Set post and steel rifle barrel for corner, from which new trees:
Red Fir 14" dia., bears N.10°E., 297 lks.
A B.Ok 24" dia., bears N.20¼°W., 650 lks.
No other trees near.

Douglas Co. Surveyors Office - Ben B. Irving; James W. Byron, Ray Irving - Work done for County Engineer, Rd. #38 - Feb. 1954 - C.S. File 46/36

Corner renewed from old BTs standing and in good condition. We find 24" B.Oak N.29°30'W. instead as recorded N.20¼°W. Distance OK.
Set a 3" Iron pipe with ½ iron rod inside, 14" below surface. Blazed and scribed the new trees:
Apple tree, 6" dia., S.56°W., 173.0 ft. mkd. S8 CS BT.
Maple 12" dia., N.76°W., 226.7 ft. mkd. S5 CS BT.

GLO resurvey by Hans W. Thielsen, under Group #316, Surveyed July/Aug. 1955 - (DCSO records Vol. 28 Page(s) 11773)

The sec. cor, perpetuated with an iron pipe 3" dia., 14" below ground.
from which a bearing tree mkd. by the County in 1916:
A B.Oak 44" dia., bears S.30¼°W., 650 lks. dist., with marks 29 S R uncovered.
and bearing trees marked by he County in 1954:
An Apple, 6" dia., bears S.56°W., 262 lks. dist. mkd. S8 CS.
A Maple 20" dia., bears N.76°W., 343 lks. mkd. S 5 CS.
At the cor. point
Set an iron post, 3 ft. long, 2" dia., 35" in the ground, with brass cap marked:
(Cont. Next Page)

TOWNSHIP 29 RANGE 07 POINT IDENTIFIER # 300600

PRIMARY CORNER DESCRIPTION Sec. Cor. for 4, 5, 8 and 9

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

T	29	S	R	7	W
	S	5	S	4	
	S	8	S	9	
				1955	

from which a new bearing tree:

A Maple 14" dia., bears N.10°E., 378 lks. dist., mkd. T29S R7W S4 BT.

No other trees available.

Reset the 3" pipe alongside the iron post.

Fd. 1955 Brass cap and 3 references, BLM survey by Berry and Popken, 1973 (DCSO records, Vol. 39 Pgs.15805-06)

Douglas Co. Surveyors Office - Randall Smith and Stephen Flause - Dec. 12, 1989 - C.S. File 64/3

Found - 1955 GLO 2½" dia. brass cap on a 2" O.D. iron pipe, 4" below ground. BC/IP leans 0.3 ft. northeast of plumb position.

A 3" O.D. plumb Iron pipe 4" below ground. I.P. is along southwest side of GLO BC/IP.

14" now 19" dia. 1 ft. high Maple stump with rotted out center. A lower blaze is visible and scribe mark "S" found bears N.10°E., 249.5 ft. (agrees w/rec.)

Set GLO brass cap/iron pipe returned to plumb position.

New Accessories:

23" dia. Maple double blazed and scribed "T29S R7W S4 CS BT" bears N.12¼°E., 258.0 ft.

8" dia. Pear tree, bark flattened and bark scribed "T29S R7W CS BT" bears N.63½°E., 324.0 ft.

5/8" x 30" long Iron rod with DCSO alum. cap stamped "BO 1" bears N.20°W., 147.7 ft. (in R/W fence line)

Corner lies approx. 175 ft. South of County Road in an open pasture. Monuments re 4" below ground.

FD. Ok by D. Edwards, 1/2008 - M155-3

Fd. as per renewal by N. Hibbs, 1/2013 - M157-69