

PRIMARY CORNER DESCRIPTION Sec. Cor. for 10, 11, 14 and 15

Alias	Description
Alias	Description
Alias	Description
Alias	Description

Original - Nathaniel Ford, under Contract #44 dated May 30, 1854 (DCSO records, Vol. 15 Page 6528)

-
- Set a post cor. of secs. 10, 11, 14 and 15, from which
- A Laurel 18" dia., bears S.18°W., 50 lks. dist.
 - A Laurel 6" dia., bears S.30°E., 53 lks.
 - A Laurel 4" dia., bears N.58°W., 17 lks.
 - A Laurel 5" dia., bears N.40°E., 15 lks.

GLO resurvey by Hans W. Thielsen under Group #346 - Surveyed 1957 - (DCSO records Vol. 28 Page(s) 12151-52)

The Sec. cor., determined at record bearing and distance from the only remaining original bearing tree:

An uprooted Madrona 18" dia., with faint scribe marks visible on decayed blaze, the stump hole of which bears S.18°W., 50 lks.

At the cor. point

Set an iron post, 3 ft. long, 2" dia., 28" in the ground, with brass cap marked:

T29S R7W
S10|S11
S15|S14
1957

from which new bearing trees:

- A Fir 12" dia., bears N.77½°E., 44 lks. dist. mkd. T29S R7W S11 BT.
- A Fir 13" dia., bears S.70½°E., 30 lks. dist., mkd. T29S R7W S14 BT.
- A Fir 7" dia., bears S.51½°W., 79 lks. dist., mkd. T29S R7W S15 BT.
- A Fir 10" dia., bears N.65°W., 41 lks. dist., mkd. T29S R7W S10 BT.

Clifford Byrden - For: Roseburg Lumber Co. - May/June 1956 - M 2-46 and C.S. File 42/158

Found - Old orig. 18" Laurel, S.18°W., 50 lks., found by R.C. Grant in 1951. This tree is down and rotted out.

- New BTs
- 20" Fir N.36°E., 20.6 ft.
 - 14" Fir N.40°W., 34.9 ft.
 - 12" Fir S.79½°W., 8.8 ft.
 - 22" Fir S.22°30'E., 8.5 ft.

All trees scribed R.E. 3937 BT.

Set 4" x 4" x 4 ft. Fir post.

NOTE: The above corner description is from a "voided" survey M 2-46 dated June 7, 1956.

(Cont. Next Page)

PRIMARY CORNER DESCRIPTION Sec. Cor. for 11, 10, 14 and 15

Alias	Description
Alias	Description
Alias	Description
Alias	Description

From evidence researched from M 2-46 and C.S. File 42/158 and M 5-41, it is felt that this corner is still valid and not "voided". BLM survey dated April 1957, does not mention finding these BTs. This corner info. recorded, Jan. 15, 1985 by this office. Virginia Laugen per Fritz Ingram.

BLM Survey by Wayne Rogers under Group #1208, Surveyed, Aug. 1984/Jan. 1985 - (DCSO records Vol. 47 Page(s) 17980)

The cor. of secs., monumented with an Iron post, 2" dia., firmly set, projecting 8" above ground, with 1957 brass cap. from which the remains of bearing trees mkd. by Thielsen:

A Fir snag 16" dia., bears N.74°E., 39 lks. dist., with healed blaze. (Rec. S.77½°E., 44 lks.)

A sawed Fir stump 12" dia., bears S.70½°E., 26 lks. dist., with healed blaze. (Rec. 30 lks.)

A sawed Fir stump 14" dia., bears N.65°W., 41 lks. dist., with healed blaze.

and the remains of bearing trees mkd. by Clifford Bryden, Engineer #3937, during an unrecorded survey in 1956:

A Fir snag 24" dia., bears N.36°E., 30 lks. dist., with healed blaze.

A sawed Fir stump 24" dia., bears S.19½°E., 12½ lks. dist. with healed double blaze.

A Fir 17" dia., bears S.76°W., 15½ lks. dist., with healed double blaze.

and a new bearing tree:

A Fir 11" dia., bears S.31½°E., 22 lks. dist., mkd. T29S R7W S14 BT.

No other suitable trees available.

Corner is located in the SE cor. of a logged area, edge bears N. and W.

Fd. OK, April 1991, M 113-6

BLM Dependent Resurvey by Kenneth W. Saveland, Cadastral Surveyor, under Group No. 2270, Surveyed May/Aug. 2009 - (DCSO records Vol. 57 Page(s) 22748-9)

The cor. of secs. 10, 11, 14, 15, monumented with an iron post, 2" dia., firmly set, projecting 12 ins. above ground, with brass cap (properly) mkd. from which the remains of BTs mkd. by Thielsen in 1957

A fir snag, 15" dia., bears N.74°E., 25.7 ft., with a healed blaze.

A sawed fir stump, 13" dia., bears S.70½°E., 19.5 ft., with a healed blaze. (Record, 17.2 ft.) CONT. NEXT PG

PRIMARY CORNER DESCRIPTION Sec. Cor. for 10, 11, 14 and 15

Alias	Description

A sawed fir stump, 14" dia., 7 ft. high, bears N.65°W., 25.9 ft., with a healed blaze. (Record, 27.1 ft.)
and the remains of bearing trees mkd. by Bryden

A decayed fir stump, size indeterminate, bears N.36°E., 19.8 ft., alongside of which is a down, decayed fir, size indeterminate, with no marks visible on an opened healed blaze.

A sawed fir stump, 27" dia., bears S.19½°E., 8.3 ft., with fragmentary scribe marks visible on a partially healed blaze.

A fir, 26" dia., bears S.76°W., 8.4 ft., with a healed double blaze. (Record, 10.2 ft.)
and a bearing tree mkd. by Rogers

A fir, 19" dia., bears S.34°E., 15.9 ft., with a healed blaze. (Record, S.31½°E., 14.5 ft.)
and new bearing trees

A fir, 17" dia., bears N.28½°E., 75.7 ft., mkd. T29S R7W S11 BT.

A fir, 4" dia., bears N.70°W., 36.4 ft., mkd. T26S R7W S10 BT.

Corner is located S.10°W., 2.0 ft., from a wood fence post at the intersection of a broken down barbed and woven wire fence, extending N. and E., on a NW. slope.

Latitude: 43°03'25.22"N. Longitude: 123°30'24.41"W.
(NAD 83 (CORS))