

Alias _____ Description _____
 Alias _____ Description _____
 Alias _____ Description _____
 Alias _____ Description _____

GLO Survey - W.H. Byars - contract #152 dated June 3, 1871
 (DCSO records Vol. 17 Pg. 7232)

 Set post cor. to secs. 2, 3, 34, & 35 from which
 A Laurel, 5" diam., bears N.40°E., 8 lks.
 A Laurel, 6" diam., bears S.75°E., 6 lks.
 A Laurel, 6" diam., bears S.10°W., 18 lks.
 A Laurel, 8" diam., bears N.60°W., 17 lks.

GLO Resurvey - William H. Byars, Deputy Surveyor, Under
 Contract No. 456, dated July 28, 1882 (DCSO records Vol. 15
 Page(s) 6549)

 At the cor., which is a post, 4" square, firmly set in the
 ground and mkd. T29S., S35 on NE. face, and R7W S2 on the SE.
 face, T30S S3 on the SW. face & S34 on the NW. face; also 2
 notches on the East angles, and 4 notches on the West, and
 from which,
 A Laurel, 5" diam., bears N.40°E., 8 lks., mkd. T29S R7W
 S35 BT.
 A Laurel, 6" diam., bears S.75°E., 6 lks., mkd. T30S R7W
 S 2 BT.
 A Laurel, 6" diam., bears S.10°W., 18 lks., mkd. T30S R7W
 S3 BT.
 A Laurel, 8" diam., bears N.60°W., 17 lks., mkd. T29S R7W
 S34 BT.

GLO Re-establishment of corners - Fred Mensch, U.S. Deputy
 Surveyor - under date of April 18, 1924 (DCSO Vol. 14 Page
 5978-79)

 Intersect the Byar's N. bdy. of T30S R7W, 76 lks.. W. of the
 Byars' cor. of secs. 2, 3, 34, & 35 which is a fir post, 6"
 sq., 12" above ground properly marked; the bearing trees have
 all rotted down, but on the NW. and SE. logs dim marks can be
 found.

Along the W. side of the post
 Set an iron post, 3 ft. long, 3" diam., 27" in the ground,
 for SE. cor. of T29½S R7W and cor. of secs. 2, 3, 34, &
 35, with brass cap marked:

T29½S	T29S
R7W	R7W
S34	S35
S3	S2
T30S	R7W
1924	

(Cont. Next Page)

Alias _____ Description _____
 Alias _____ Description _____
 Alias _____ Description _____
 Alias _____ Description _____

from which
 A fir, 16" diam., bears N.52°E., 68 lks., mkd. T29S R7W S35 BT.
 A fir, 14" diam., bears S.75°E., 44 lks., mkd. T30S R7W S2 BT.
 A cedar, 8" diam., bears S.26°W., 21 lks., mkd. T30S R7W S3 BT.
 A fir, 30" diam., bears N.29°W., 83 lks., mkd. T29½S R7W 34 BT.

James W. Byron, Dep. Co. Surveyor - John Powell & Dale McFarland - May/June 1962 - C.S. 49/139

 Renewed corner to T29½ T29S
 S34 | S35 R7W
 S 3 | S 2 T30S
 Found - Brass cap at corner & all BT's except NE. BT.
 New BT- 6" R. Fir, bears N.39°E., 25 ft., scribed S35 CS BT.

BLM resurvey by Harvey Wofford, G. Steven Popken, & James J. Carlson, instructions dated August 29, 1974 under Group #851. Surveyed Sept. 1974/May 1976 (DCSO records Vol. 39 Page 15817-18)

 from the corner, monumented with an iron post, 3" diam., firmly set projecting 15" above ground, with brass cap mkd.
 T29½S | T29S
 R7W |
 S34 | S35
 S 3 | S 2
 T30S | R7W
 1924
 from which the remains of bearing trees mkd. by Mensch
 A fir, 25" diam., bears N.54°E., 68 lks., with healed double blaze.
 A root hole, bears S.75°E., 42 lks., with a down fir alongside, 15" diam., with healed double blaze. (Record, 44 lks.)
 A cedar snag, 9" diam., bears S.26°W., 21 lks., with scribe mks. R7W visible on open double blaze.
 A fir, 38" diam., bears N.27½°W., 86 lks., with healed double blaze. (Record, N.29°W., 83 lks.)
 and the remains of a bearing tree mkd. by the Co. Surveyor in 1962
 A fir snag, 8" diam., bears N.34°E., 38 lks., with scribe mks S35 CS BT visible on open double blaze.
 (Cont. Next Page)

TOWNSHIP 29 RANGE 07 POINT IDENTIFIER # 507100

PRIMARY CORNER DESCRIPTION SW Cor. Sec. 35 (SE Cor. T29¹/₂S R7W)

Alias	Description
_____	_____
_____	_____
_____	_____
_____	_____

and new bearing trees

A fir, 13" diam., bears S.54°E., 69½ lks., mkd. T30S R7W S2 BT.

A fir, 8" diam., bears S.36°W., 39½ lks., mkd. T30S R7W S3 BT.

Fd. Ok. - Howard Johnstone - Jan. 30, 1981 - M86-77

Douglas Co. Surveyors office - Randall Smith & Stephen Flause
- Dec. 19, 1991 - C.S. 64/21-14

Found - A 3½" diam. 1924 GLO brass cap on a 3" O.D. Iron pipe protruding 14" above ground.

16" now 27" diam., D. Fir with a fully healed double blaze, bears N.52½°E., 44.9 ft. (Rec. N.54°E., 44.9ft) 1924 GLO.

1924 GLO S.75°E., 27.7 ft. BT is gone.

8" now 11" diam., 2 ft. high Cedar stump, tree is down alongside stump, scribing visible "R7" bears S.26°W., 13.9 ft. (agrees with rec.) 1924 BT.

30" now 36" diam., D. Fir with a fully healed double blaze, bears N.27½°W., 56.8 ft. (agrees with rec.) 1924 BT.

6" now down and rotting 6" D. Fir with illegible scribing visible, bears N.34°E., 25.1 ft. (agrees with rec.) Byron.

13" now 12" diam., 7 ft. high D. Fir stump with a fully healed single blaze, bears S.51°E., 13.9 ft. (rec. S.54°E., 45.9 ft.) (tagged by B. Moyer in 1958, tag reads N.24½°E., 21 lks.) unsure of reason for bad brg's and dist. 1924 GLO.

8" now 13" diam. W. Fir with a fully healed single blaze bears S.36°W., 25.5 ft. (rec. S.36°W., 26.1 ft., to center of trunks) 1964 BT.

New BT - 8" D. Fir double blazed and scribed "T29S R7W S35 CS BT" bears N.43°E., 8.4 ft.

corner lies at the intersection of a south and east running cut lines, clear cut to the southeast. Approx. 125 ft. north of a gravel road.