

TOWNSHIP 29 RANGE 07 POINT IDENTIFIER # 507200

PRIMARY CORNER DESCRIPTION Sec. cor. of 26, 26½, 34½, & 35

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Retracement GLO Survey - Roy T. Campbell, Dep. Surveyor, -
Con. #789, Aug 21, 1909 (DCSO records Vol. 15 Page(s) 6560)

I Set a conglomerate stone, 18x12x10", 12" in the ground, for
C.C. for secs. 26 & 35, marked C.C. on E., with 1 groove on
S. and 2 grooves on E. face, from which:

A fir, 30" diam., bears N.12°45'E., 45 lks., mkd. T29S R7W
S26 BT.

A fir, 30" diam., bears S.31°45'E., 40 lks., mkd. T29S R7W
S35 BT.

Re-establishment of corners - Fred Mensch, U.S. Deputy
Surveyor - under date of April 18, 1924 (DCSO records Vol. 14
Page(s) 5976-77)

Intersect E. and W. line, 19 lks. W. of Campbell's closing
cor. of secs. 26 & 35, which is a conglomerate stone,
6x12x10" above ground, mkd. CC on E., with 1 groove on S. and
2 grooves on E. face; from which (the original bearing trees)

A fir, 20" diam., bears N.12 3/4°E., 45 lks., mkd. T29S
R7W S26 BT.

A fir, 24" diam., bears S.31 3/4°E., 40 lks., mkd. T29S
R7W S35 BT.

I change this cor. to cor. of secs. 26, 26½, 34½, & 35;
obliterate marks on the stone and reset same 12" in the
ground, mkd. S. 26 on NE., S35 on SE., 34½ on SW. and 26½
on NW. face, with 1 notch on S. and 2 notches on E. edge;
from which (additional new bearing trees)

A fir, 20" diam., bears S.76°W., 35 lks., mkd. T29S R7W
S34½ BT.

A fir, 12" diam., bears N.55°W., 72 lks., mkd. T29S R7W
S26½ BT.

James W. Byron, Dep. Co. Surveyor - John Powell & Dale
McFarland - May 1962 - C.S. 49/139-57

Found - Stone at corner & Orig. NE. & SE. BT's. NE BT
shows
scribing.

Set Brass cap alongside corner stone & mkd. S26½|S26
County Surveyors Office, 1962 T29S S34|S35 R7W

Douglas Co. Surveyors Office - R.B. Kimberling, K. Cheney, &
S. Flause - June 13, 1977 - C.S. 59/34-35

Found - A 1962 Douglas Co. Brass cap properly mkd on a
1"x30 I.P. 10" out of ground at a 45° angle.
(apparently had slid down hill) (Byron) (Cont.)

TOWNSHIP 29 RANGE 07 POINT IDENTIFIER # 507200

PRIMARY CORNER DESCRIPTION Sec. cor of 26, 26½, 34½, & 35

Alias	_____	Description	_____
Alias	_____	Description	_____
Alias	_____	Description	_____
Alias	_____	Description	_____

A 1"x27" I. pipe buried along side cap
A conglomerate stone 6"x12"x10" buried 24" in ground.
A 30" D.Fir now 30" bears S.31°45'E., 26.4 ft (rec. as a 24" tree 1924) with visible healed blaze.
A 30" D.Fir now 28" bears N.15°E., (rec. N.12°45'E.) 29.7 ft. (Recorded as a 20" tree in 1924 Resurvey) visible healed double blaze.
Replace Douglas County Brass cap in proper position stamped "Reset 1977".
A conglomerate stone 6"x12"x10" buried 24" underground on east side of brass cap.
A 1"x27" I. pipe on NE. side of cap.
No other trees available.

David Edwards - 10/22/2009 - C.S. File 65/66-41

1962/1977
Found - Douglas County Surveyor brass cap found in good condition. (properly marked)
All of the previously marked bearing trees are either snags or are gone.
New - An 11" dia. Maple bears N.49°E., 34.1' scribed T29S R7W S26 BT
A 16" dia. Fir bears S.41°E., 52.8' scribed T29S R7W S35 BT
A 10" dia. Fir bears S.12°W., 6.3' scribed T29S R7W S34½ BT
A 15" dia. Fir bears N.49°W., 27.3' scribed T29S R7W S26½ BT
Note - All new BTs measured to center of tree at root crown.
Compass decl. 18°E.