

TOWNSHIP 29 RANGE 07 POINT IDENTIFIER # 600240

PRIMARY CORNER DESCRIPTION 1/4 Cor. for secs. 25 and 26

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

BLM survey by Roy T. Campbell, under Group #789 dated Aug. 21, 1909, (DCSO records Vol. 15 Page(s) 6561)

Set a Fir post, 3 ft. long, 4" square, 24" in the ground, for 1/4 sec. corner, marked 1/4 S26 on W. and 25 on E. face, from which

A Fir 30" dia., bears S.61°E., 93 lks. dist., mkd 1/4 S25 BT
A Fir 18" dia., bears S.63°30'W., 39 lks. dist., mkd. 1/4 S26 BT.

Douglas Co. Surveyors Office - Ben B. Irving - N.E. Richardson; Frank Royer; Robinette; Bill Weightman - May 1934 - C.S. File 37/171 and M 1-27

Post rotted off. Original BTs as described in original field notes. Set Fir post 4" x 4" x 36".

Douglas Co. Surveyors Office - John Powell & Crew - Oct. 1969 - C.S. File 49/139-126

Not found. Old line tags 3 1/2 Talleys south of 1/4 cor. This cor. probably taken out by old roads & logging, then burnt.

BLM Dependent Resurvey by Kenneth W. Saveland, Cadastral Surveyor, under Group No. 2270, Surveyed May/Aug. 2009 - (DCSO records Vol. 57 Page(s) 22741)

Point for the 1/4 sec cor. of secs 25 and 26 at proportionate dist.; there is no remaining evidence of the original cor. Set a stainless steel post, 28" long, 2 1/2" dia., 24" in the ground, with brass cap mkd.

T29S R7W
1/4
S 26 | S 25
2009

from which

A fir, 18" dia., bears S.53 3/4°E., 25.0 ft. mkd. 1/4 S25 BT
A fir, 14" dia., bears S.62 1/2°W., 43.8 ft., mkd. 1/4 S26 BT.

Deposit a magnet in a white plastic case at the base of the stainless steel post.

Corner is located W, 4.5 ft. from a woven wire fence extending N and S.