

TOWNSHIP 29 RANGE 07 POINT IDENTIFIER # 640200

PRIMARY CORNER DESCRIPTION 1/4 Cor. for secs. 25 & 36

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

Campbell, 1910 Pg. 6557  
Set a Fir post, 4" square, 3 ft. long, 24" in the ground, for  
¼ sec. cor., mkd. ¼ S25 on N. and 36 on S. face, from which  
A Madrona, 18" dia., bears S.40°W., 28 lks. dist., mkd. ¼  
S36 BT.  
A Fir 30" dia., bears N.80°E., 13 lks. dist., mkd. ¼ S25  
BT.

Douglas Co. Surveyors Office - Ben B. Irving, Deputy - Wit:  
N.E. Richardson; Frank Royer; Robinette; Bill Weightman - May  
1934 - C.S. File 37/171 and M 1-27

-----  
Original BTs as described in Govt. field notes.  
Set Fir Post 4" x 4" x 36" --¼ S25-36.

Douglas Co. Surveyors Office - James Byron, Deputy - Dale  
McFarland; John Powell - April/May 1962 - C.S. File 49/139-55

-----  
Found - Orig.30" now 34" Fir, N.80°E., 8.6 ft. shows good  
scribing on old face "B".  
SW BT, now down.

Set brass cap at cor. and along West side of 36" Fir log mkd:  
County Surveyors ¼ S 25 T29S R7W  
Office, 1962 S 36

New BTs -9" Fir bears N.64°E., scribed ¼ S25 CS BT. (Dist.  
20.0 ft.)  
10" R.Fir bears S.1°E., 29.5 ft. scribed ¼ S36 CS  
BT.

North-South logging road 10 ft. West of ¼ corner.

BLM rehabilitation of certain corners, Timothy J. Moore,  
Cadastral Surveyor & Robert H. Browning, Surveying Tech.,  
under Group #2000, Surveyed July 2002, - (DCSO records Vol.  
54 Page(s) 21144-5)

-----  
The ¼ sec. cor. of secs. 25 & 36, perpetuated by the Douglas  
County Surveyors Office, in 1962, monumented with an iron  
pipe, 1¼" dia., firmly set, projecting 15" above ground, with  
brass cap mkd. COUNTY SURVEYORS OFFICE

T29S R7W  
¼ S 25  
S 36  
1962

from which the remains of an original bearing tree  
A fir stump, 28" dia., bears N.80°E., 8.6 ft., with  
fragmentary scribe marks visible on opened blaze.

continued next page

TOWNSHIP 29 RANGE 07 POINT IDENTIFIER # 640200

PRIMARY CORNER DESCRIPTION 1/4 Cor. for secs. 25 & 36

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

and the remains of bearing trees mkd. by the Douglas County Surveyors Office  
A decayed fir stump, 19" dia., bears N.61 $\frac{3}{4}$ °E., 19.9 ft., with no marks visible.  
A fir, 25" dia., bears S.3°E., 29.2 ft., with a healed blaze.  
and a new bearing tree  
A Cedar, 8" dia., bears N.56°W., 42.3 ft., mkd.  $\frac{1}{4}$  S25 BT. Each new bearing tree has a 2 $\frac{1}{2}$ "x  $\frac{1}{4}$ " magnetic nail (Mag Nail) driven at the base right side-center.  
Corner is located 24.0 ft. East of a graveled road, 20 ft. wide, which bears N.15°E. and S.25° W.  
The geographic position (NAD 1983 (CORS)) of this cor. as determined by NAVSTAR GPS, utilizing dual frequency, carrier phase GPS receivers, (Trimble 5700), relative to the National Spatial Reference System, is as follows:  
Latitude: 43°00'48.86"N., Longitude: 123°28'32.21"W.