

PRIMARY CORNER DESCRIPTION SE Cor. Wm. P. Day DLC #44

Alias	Description
_____	_____
_____	_____
_____	_____
_____	_____

<p>DLC Survey by J.A. Burnett, under Contract #75 dated Nov. 22, 1856 - DLC Volume, Page 589</p> <p>-----</p> <p>Set post from which A W.Ash 8" dia., bears N.70°W., 83 lks.</p>
<p>J.W. Cole, Surveyor - Wit: N.E. Richardson; J.B. Stobie - April 25, 1923 - Vol. 3 Pgs. 148-149</p> <p>-----</p> <p>This corner was renewed from the original BT which was a W.Oak instead of W.Ash as called in the field notes. I set an Iron pipe 1¼" x 36" in dia., from which a W.Oak 14" dia., N.70°W., 83 lks. A Fir line tree called for in field notes bears West, 267.3 ft.</p>
<p>B.B. Irving - March 20, 1928 - No record source, see "Old" corner book, Page 135</p> <p>-----</p> <p>Located this corner. Orig. BT as described by Cole in place. Line tree still in place. Both trees killed when slashing was burned. Set new BT: A 12" Fir S.2°W., 96.6 ft. scribed Cl. 44 C.S. B.T.</p>
<p>BLM resurvey by Donald Beck, Cadastral Surveyor, under Group #584 - Surveyed July 1965 - (DCSO records Vol. 33 Page(s) 13882-83)</p> <p>-----</p> <p>The SE. Cor. Wm. Day DLC #44, perpetuated and recorded by Cole in 1923, when the original bearing tree was still in existence, monumented with an iron pipe 1¼" dia., firmly set, extending 3" above ground. At the corner point Set an iron post, 28" long, 2 1/2" dia., 22" in the ground, with brass cap mkd: DLC 44 T 29 S R 8 W S 31 1965</p> <p>from which A Fir 8" dia., bears N.25¼°E., 12 lks. dist. mkd. S31 BT. A Fir 6" dia., bears S.41°W., 39½ lks. dist. mkd. S31 BT. A Fir 11" dia., N.76°W., 25½ lks. dist. mkd. DLC 44 BT. A Fir 13" dia., N.28 3/4°W., 25 lks. dist. mkd. DLC 44 BT. Reset the iron pipe alongside the iron post.</p>
<p>Fd. OK, Nov. 1989 by Laney - M 109-20</p>