

TOWNSHIP 29 RANGE 08 POINT IDENTIFIER # 100140

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Sec. 31; & 36, T29-9

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GL0 survey by Dennis Hathorn, Deputy Surveyor under Contract #57, dated April 12, 1855 - (DCSO records Vol. 16 Page(s) 6575)

Set ¼ sec. post, from which
A Fir 36" dia., bears N.42°W., 9 lks. dist.
A Fir 15" dia., bears S.33°E., 33 lks. dist.

G.G. Stewart - Wit: W.S. Crear; E.J. Kennedy - May 22, 1922
-Vol. 4 Page 121

Renewed O.B.T.s marks. Set Iron pipe for corner.

Douglas Co. Surveyors Office - James Byron, Deputy - Milo Godfrey; S. Bilow, crew - July 17, 1958 - C.S. File 49/100-4

Found - Fir stump, now 28" dia., S.33°E., 21.8 ft. Chopped out lower blaze and found "BT" scribed in wood. More recent bark scribing "¼ S BT"
Fir stump, now 48" dia., N.42°W., 5.9 ft. Lower scar has been chopped into but not opened to original blaze.

Set Brass cap at cor. mkd: County Surveyors Office
T 29 S
R9W S36|S31 R8W
1958

New BTs- 12" W.Fir N.11°E., 32.3 ft. scribed ¼ S31 CS BT.
8" W.Fir S.28°W., 13.0 ft. scribed ¼ S36 CS BT.

Fd. and used in BLM resurvey by Donald Beck, Cadastral Surveyor, under Group #584 - Surveyed July 1965 - (DCSO records Vol. 33 Page(s) 13881)

Add the marks BLM 1965 to top of brass cap.

Fd. and used in BLM resurvey by Wayne L. Rogers, Cadastral Surveyor and Robert H. Browning, Surveying Technician, under Group #1583 - Surveyed April/June 1991 - (DCSO records Vol. 49 Page(s) 18670-71)

Fd. OK, Feb. 1997 by D. Bentz - M 126-39