

TOWNSHIP 29 RANGE 08 POINT IDENTIFIER # 100340

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Sec. 19; & 24, T29-9

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by Dennis Hathorn, Deputy Surveyor under Contract #57, dated April 12, 1855 - (DCSO records Vol. 16 Page(s) 6574)

Set ¼ sec. post, from which
A W.oak 20" dia., bears S.87°E., 924 lks. dist.
An Ash 12" dia., bears N.76½°E., 887 lks. dist.
Reed's house bears N.12°W.

Cole - Field Book 48 Page 11 - Aug. 1920

Found Oak rotten.

Arthur Boyer, Eng. #1581 - Wit: Bernard Denn; W.E. Howard;
Leo Denn - Feb. 7, 1955 - C.S. File 41/353 A & M 61-2

Set this corner from OBT in Section 19.
Drove a 1/2" x 20" iron pipe for corner, from which
A 1/2" x 23" Iron pipe in fence line, bears S.89°38'W.,
20.0 ft.
A 1" x 19" Iron pipe in fence line, bears N.89°38'E., 18.7
ft.
Corner is in County Road. Orig. BT in sec. 19 still
standing.

Survey by Herbert Northcraft - For: James Atterberry -
July/Aug 1976 - M 61-18

Did not dig up Co. Road but found witness corners and witness
tree as shown on M 61-2.
Set 1/2" R.R. Spike in black top.

Fd. OK, Dec. 1989 by B. Rogers - Partition #1990-0004