

PRIMARY CORNER DESCRIPTION Sec. Cor. for 31 & 32, (South)

Alias	Description
Alias	Description
Alias	Description
Alias	Description

GLO survey by Dennis Hathorn, Deputy Surveyor under Contract #57, dated April 12, 1855 - (DCSO records Vol. 16 Page(s) 6578)

-
- Set post cor. secs. 31, 32, 5 and 6, from which
- A Fir 30" dia., bears S.50°E., 3 lks. dist.
 - A Fir 15" dia., bears S.87°W., 74 lks. dist.
 - A Hemlock 15" dia., bears N.75°W., 38 lks. dist.
 - A Hemlock 15" dia., bears N.33°E., 26 lks. dist.

GLO survey by W.H. Byars, Deputy Surveyor under contract # 456 dated July 28, 1882 (DCSO records Vol. 16 Page(s) 6613)

Old cor. for secs. 5, 6, 31 and 32 which is a post 4" sq., firmly set in the groun mkd. T29S S32 on NE. face; T30S S5 on SE. face; S6 on SW. and S31 on NW. face, and from which (Found and describes 4 BTs as above)

Douglas Co. Surveyors Office - James Byron, Deputy - Milo Godfrey; S. Bilow, crew - Sept. 1958 - C.S. File 49/100

Found - Orig. 15" now dead 24" hemlock, N.33°E., 17.2 ft. I open and find good scribing "BT".

- Orig. 30" partly rotted Fir snag S.50°E., 2.0 ft.

Stump holes that check bearing and dist. for SW. and NW. BTs.

Drove 3/4" x 30" Rod at corner.

New BTs- 12" Hemlock bears N.2°W., 79.0 ft. scribed S31 T29S R8W CS BT.

- 16" Hemlock bears S.61°W., 38.5 ft. scribed S6 T30S R8W CS BT.

(Sketch in file shows exact location of corner.

BLM resurvey by Donald Beck, Cadastral Surveyor, under Group #584 - Surveyed July 1965 - (DCSO records Vol. 33 Page(s) 13877-78)

The Sec. Cor., perpetuated and recorded by Byron in 1958, monumented with an iron rod 3/4" dia., firmly set flush with the ground, from which the remains of the orig. BTs:

- A Hemlock snag 18" dia., bears N.33°E., 26 lks. dist. mkd. T on an opened blaze.
- A burned Fir stump 20" dia., bears S.50°E., 4 lks. dist., no marks remaining. (Rec. 3 lks.)

and bearing trees mkd. by Byron

- A Hemlock 16" dia., bears S.60°W., 58½ lks. dist. mkd. T30S R8W S6 CS BT on a double blaze.

(Cont. Next Page)

TOWNSHIP 29 RANGE 08 POINT IDENTIFIER # 200100

PRIMARY CORNER DESCRIPTION So. Sec. Cor. for 31 & 32 only

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

A Hemlock 12" dia., bears N.3¼°W., 120 lks. dist. mkd.
T29S R8W S31 CS BT on a double blaze.

At the corner point

Set an iron post, 28" long, 2 1/2" dia., 22" in the ground,
with brass cap mkd:

T 29 S R 8 W

S 31 S 32

T 30 S R 8 W

S 6

1965

Reset the iron rod alongside the iron post.

BLM Resurvey by Dale T. Bedell and Bryan S. Seibold,
Cadastral Surveyors - Under Group #1494, Surveyed July
1989/April 1993 - (DCSO records Vol. 50 Page(s) 19019-20)

The sec. cor., monumented with an iron post 2½" dia., firmly
set, projecting 4" above ground, with brass cap mkd. in
1965, from which the remains of bearing trees mkd. by Byron
in 1958

A rotted, sawed Hemlock stump bears S.60°W., 58½ lks.
dist., with a down Hemlock 20" dia., alongside, with
scribe marks T30S R8W S6 CS visible on open blaze.

A rotted Hemlock stump, bears N.3¼°W., 120 lks. dist.,
with down Hemlock, 10" dia. alongside, with fragmentary
scribe marks visible on partially healed blaze.

and new bearing trees

A Fir 4" dia., bears N.54°E., 42½ lks. dist., mkd. X BT.

A Fir 6" dia., bears N.25½°W., 104 lks. dist. mkd. T29S
R8W S31 BT.

Mark Smalley - For: Roseburg Resources & Moore Mill - 8/2002
- M 137-50

Found - 1965 BLM brass cap on an iron pipe
8" Fir N.54°E., 28.0' healed.

10" Fir N.25½°W., 68.6' healed.

Scribed- 6" Hemlock S.75½°E., 19.9' "S6 BT"

7" Hemlock S.24°W., 21.6' "S6 BT"