

TOWNSHIP 29 RANGE 08 POINT IDENTIFIER # 200140

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 31 and 32

|             |                   |
|-------------|-------------------|
| Alias _____ | Description _____ |
| Alias _____ | Description _____ |
| Alias _____ | Description _____ |
| Alias _____ | Description _____ |

GL0 survey by Dennis Hathorn, Deputy Surveyor under Contract #57, dated April 12, 1855 - (DCSO records Vol. 16 Page(s) 6600)

-----  
Set ¼ sec. post, from which  
A Fir 60" dia., bears S.22°E., 15 lks. dist.  
A Fir 40" dia., bears N.7°W., 41 lks. dist.

A. Boyer - 1939 - C.S. File 16/25

-----  
(Describes two original BTs.)  
Marked two trees:  
57" Fir N.13°W., 23.7 ft.  
60" Fir, S.40°E., 7.5 ft.  
Trees marked ¼ S only, on bark.

Douglas Co. Surveyors Office - James Byron, Deputy - Milo Godfrey; S. Bilow, crew - Sept. 1958 - C.S. File 49/100-35

-----  
Found - Scribed "CS" stake bears S.20°W., 3.7 ft.  
Orig. 60" now 60" rotted Fir snag, S.22°E., 9.9 ft.  
I open near base and find lower part of old blaze and small scribe mark  
Orig. 40" now 48" Fir, down, N.7°W., 27.1 ft. I open and find good scribing "B".

Set Brass cap at cor. mkd: County Surveyors Office  
T 29 S R 8 W  
¼ S31|S32  
1958

New BTs- 18" Cedar bears N.54½°W., 41.0 ft. scribed ¼ S31 CSBT  
14" W.Fir bears N.20°E., 12.4 ft. scribed ¼ S32 CSBT

BLM resurvey by Donald Beck, Cadastral Surveyor, under Group #584 - Surveyed July 1965 - (DCSO recs Vol. 33 Page(s) 13884)

-----  
The ¼ sec. cor., perpetuated and recorded by Byron in 1958, monumented with an iron post 1½" dia., firmly set, extending 14" above ground, with brass cap mkd. in 1958 from which the remains of the original SE. bearing tree:  
A stump hole, bears S.22°E., 15 lks. dist.  
and bearing trees mkd. by Byron:  
A Fir 15" dia., bears N.19°E., 19 lks. dist., with scribe marks visible on partially healed double blaze.  
A Cedar 19" dia., bears N.55½°W., 62 lks. dist., mkd. ¼ S31 CS BT on a double blaze.  
Add the marks BLM 1965 to top of brass cap.

continued next page

TOWNSHIP 29 RANGE 08 POINT IDENTIFIER # 200140

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 31 and 32

|             |                   |
|-------------|-------------------|
| Alias _____ | Description _____ |
| Alias _____ | Description _____ |
| Alias _____ | Description _____ |
| Alias _____ | Description _____ |

Fd. & used on BLM resurvey by A. Bert Skeesick, Cadastral Surveyor under Group #1972, surveyed April/May 2001- (DCSO rec. Vol. 54 Page(s) 20964)

Fd. BC & 2 BTs. by Gary Smithers, 7/2007 - M153-78

BLM Dependent Retracement by Kenneth W. Saveland, Cadastral Surveyor, under Group No. 2300 Admin. file No. 1001, Surveyed March 2010 - (DCSO records Vol. 57 Page(s) 22691)

-----  
The ¼ sec. cor. of secs. 31 & 32. monumented with an iron post. 1½" dia., firmly set, projecting 17" above ground, with a brass cap (properly) mkd. from which the remains of bearing trees mkd. by the Douglas County Surveyors Office in 1958  
A fir snag, 17" dia., bears N.19°E., 12.5 ft., with a healed double blaze.  
A cedar, 30" dia., bears N.55½°W., 40.9 ft., with a healed double blaze.  
and a new bearing tree  
A fir, 12" dia., bears S.14¾°E., 29.3 ft mkd. ¼ S32 BT.