

TOWNSHIP 29 RANGE 08 POINT IDENTIFIER # 200200

PRIMARY CORNER DESCRIPTION Sec. Cor. for 29, 30, 31 and 32

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GL0 survey by Dennis Hathorn, Deputy Surveyor under Contract #57, dated April 12, 1855 - (DCSO records Vol. 16 Page(s) 6600)

Set post cor. secs. 29, 30, 31 and 32, from which
A Fir 15" dia., bears N.60°W., 48 lks. dist.
A Fir 30" dia., bears S.10°W., 175 lks. dist.
A Fir 9" dia., bears N.20°E., 103 lks. dist.
A W.Oak 12" dia., bears S.46°E., 106 lks. dist.

J.W. Cole, County Surveyor - Wit: N.E. Richardson; J.B. Stobie - April 1923 - Vol. 3 Pages 148-49 (and Described by Boyer in C.S. File 16/25)

I renewed this corner from the original bearing trees and set a pitch limb post 3" x 3" x 36", also an Iron pipe 1¼" x 30", from which original BTs:

A Fir 20", dead, standing, bearing scribe marks, bears N.60°W., 48 lks.
A 15" Oak nearly dead, showing scribe marks, bears N.77°E., 106 lks.
A Fir 30" dia., showing scars, bears S.8°W., 155.5 ft. or 175 lks.

Marked new trees:

A Fir 18" dia., S.49°30'E., 29.0 ft.
A Fir 30" dia., N.60°30'W., 53.0 ft.

Douglas Co. Surveyors Office - James Byron, Deputy - Milo Godfrey; S. Bilow, crew - Oct. 1958 - C.S. File 49/100-42

Found - 1¼" Iron pipe, out of ground at fence corner, fences running North and West.

Cole's 18" now 22" Fir, S.49½°E., 29.0 ft., shows good scars, I do not open.

Orig. 15" Oak, record N.77°E., should be S.77°E., 69.9 ft., shows rotted face, no scribing found.

Orig. 30" now 56" Fir 115.5 ft., S.8°W., shows good bark scribing.

Cole's 20" now 24" Fir stump N.60°30'W., 53.0 ft.

Reset I.Pipe at fence corner and set 3/4" Iron rod alongside.

New BTs- 5" R.Fir bears N.63°W., 64.7 ft. scribed S30 CS BT.

12" W.Fir bears S.87°W., 27.3 ft. scribed S31 T29S R8W CS BT.

9" R.Fir bears N.61½°E., 13.7 ft. scribed S29 T29S R8W CS BT.

(Cont. Next Page)

PRIMARY CORNER DESCRIPTION Sec. Cor. for 29, 30, 31 and 32

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

BLM resurvey by Donald Beck, Cadastral Surveyor, under Group #584 - Surveyed July 1965 - (DCSO records Vol. 33 Page(s) 13885)

The Sec. Cor., perpetuated and recorded by Cole in 1923, from the remaining original bearing trees, subsequently remonumented by Byron in 1958, with an iron rod, 3/4" dia., firmly set, extending 8" above ground, from which the remains of the original bearing trees:

An Oak 20" dia., bears S.75¼°E., 104 lks., with no marks remaining on rotted open blaze. (Rec. S.46°E., 106 lks)

A sawed Fir stump 48" dia., bears S.10°W., 177 lks. 175 lks to face, with no marks remaining (Rec dist 175 lks)

and a bearing tree mkd. by Cole:

A Fir 25" dia., bears S.46°E., 43 lks. with a healed blaze

and a bearing tree mkd. by Byron:

A Fir 9" dia., bears N.59°E., 20½ lks. mkd. with a partially healed blaze.

At the corner point

Set an iron post, 28" long, 2 1/2" dia., 23" in the ground, with brass cap mkd:

T 29 S R 8 W
S 30 S 29
S 31 S 32
1965

from which new bearing trees:

A Fir 7" dia. bears S.5½°W., 141 lks. mkd. T29S R8W S31 BT

A Fir 7" dia. bears N.65°W., 128 lks. mkd. T29S R8W S30 BT

Reset iron rod alongside the iron post.

Fd. OK, Dec. 1989 by Laney - M 109-20

BLM resurvey by A. Bert Skeesick, Cadastral Surveyor under Group #1972, surveyed April/May 2001- (DCSO rec. Vol. 54 Page(s) 20960-1)

The cor. of secs. 29, 30, 31, & 32, monumented with an iron post, 2½" diam., firmly set, projecting 3" above ground, with brass cap (properly) mkd.

from which the remains of the original bearing trees

An oak, 21" dia., bears S.76¾°E., 68.6 ft., with no scribe marks visible on partially healed blaze. (Record, S.75¼°E.)

A sawed fir stump, 48" dia., bears S.8¾°W., 116.8 ft., with a healed blaze. (Record, S.10°W.)

and the remains of a bearing tree mkd. by Cole

A fir stump, 27" dia., bears S.46°E., 28.4 ft., with no marks visible.

continued next page

TOWNSHIP 29 RANGE 08 POINT IDENTIFIER # 200200

PRIMARY CORNER DESCRIPTION Sec. Cor. for 29, 30, 31 and 32

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

and a bearing tree mkd. by Byron
A fir, 17" dia., bears N.57¼°E., 13.5 ft., with a healed double blaze. (Record, N.59°E.)
and bearing trees mkd. by Beck
A fir, 20" dia., bears S.4½°W., 93.0 ft., with a healed blaze. (Record, S.5½°W.)
A fir, 27" dia., bears N.65°W., 84.5 ft., with a healed double blaze.
Corner is located approx. 40 ft E of Buck Springs Road at the intersection of barbed wire fence, extending N, E, S, & W.

BLM Dependent resurvey by Timothy J. Moore & A. Bert Skeesick, Cadastral Surveyors under Group #2097, surveyed Sept. 2004 (DCSO rec. Vol. 55 pg(s) 21284-5)

The cor. of secs. 29, 30, 31, & 32, monumented with an iron post, 2½" dia., firmly set, projecting 3" above ground, with brass cap (properly) mkd.
from which the remains of the original bearing trees
An oak, 21" dia., bears S.76¾°E., 68.6 ft., with no scribe marks visible on partially healed blaze.
A sawed fir stump, 48" dia., bears S.8¾°W., 116.8 ft., with a healed blaze.
and remains of a BT mkd. by the Douglas County Surveyors Office in 1923
A fir stump, 27" dia., bears S.46°E., 28.4 ft., with no marks visible.
and a BT mkd. by the Douglas County Surveyors Office in 1958
A fir, 17" dia., bears N.57¼°E., 13.5 ft., with a healed double blaze.
and bearing trees mkd. by Beck
A fir, 20" dia., bears S.4½°W., 93.0 ft., with a healed blaze.
A fir, 27" dia., bears N.65°W., 84.5 ft., with a healed double blaze.

Fd. BC by D. Edwards, 8/2011 - M162-80

BLM Dependent Retracement by Kenneth W. Saveland, Cadastral Surveyor, under Group No. 2300 Admin. file No. 1001, Surveyed March 2010 - (DCSO records Vol. 57 Page(s) 22691)

The cor. of secs. 29, 30, 31, and 32, monumented with an iron post, 2½" dia., firmly set, projecting 3" above ground, with a brass cap (properly) mkd.
from which the remains of original bearing trees

continued next page

TOWNSHIP 29 RANGE 08 POINT IDENTIFIER # 200200

PRIMARY CORNER DESCRIPTION Sec. Cor. for 29, 30, 31 and 32

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

An oak, 21" dia.. bears S.76¾°E., 68.6 ft., with no marks visible on decayed, partially healed double blazes.
A sawed fir stump, 48" dia., bears S.8¾°W.. 116.8 ft., with a healed blaze.
and the remains of a BT mkd. by the Douglas County Surveyors Office in 1923.
A sawed fir stump, 27" dia., bears S.46°E., 28.4 ft., with no marks visible.
and the remains of a bearing tree mkd. by the Douglas County Surveyors Office in 1958
A sawed fir stump, 19" dia., bears N.57¾°E., 13.5 ft., with a healed blaze.
and the remains of bearing trees mkd. by Beck in 1965
A fir, 23" dia., bears S.4½°W.. 93.0 ft., with a healed blaze.
A sawed fir stump, 32" dia., bears N.65°W., 84.5 ft., with a healed blaze.
and new bearing trees
A fir, 11" dia., bears N.55°E., 47.0 ft., mkd. T29S R8W S29 BT.
A fir, 5" dia., bears N.27°W., 6.6 ft., mkd. X BT.
Corner is located 40 ft. E. of Buck Springs Road, at the intersection of barbed wire fence lines extending N., E., S., and W.
Latitude 43°00'40.10"N. Longitude 123°40'53.16"W.
(NAD 1983 (CORS))