

TOWNSHIP 29 RANGE 08 POINT IDENTIFIER # 241100

PRIMARY CORNER DESCRIPTION N. 1/4 Cor. for Sec. 5 only, T30-8

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Arthur Boyer - 1939 - C.S. File 16/25

-----  
4 x 4 Cedar post, from which  
4" Cedar N.10°15'W., 4.3 ft.  
60" Cedar S.73°E., 24.0 ft.

Douglas Co. Surveyors Office - James Byron, Deputy - Milo Godfrey; S. Bilow, crew - Oct. 29, 1958 - C.S. File 49/100-43

-----  
Found - 3" x 4" Cedar stake, scribed, set by Boyer in 1939. Red Cedar now 10", N.10¼°W., 4.3 ft. blaze nearly covered but traces of scribing can be seen. I.Cedar, approx. 62" dia. with scribing "S5 CS BT" plainly visible. (Dist. to face)

Set Brass cap at cor. mkd: County Surveyors Office 1958  
T 29 S R 8 W  
South ¼ S32  
T30S R8W

Blaze and scribe one new tree in sec. 32:  
10" D.Fir N.88°W., 21.5 ft. mkd. "¼ S32 CS BT"

BLM Resurvey by Dale T. Bedell and Bryan S. Seibold, Cadastral Surveyors - Under Group #1494, Surveyed July 1989/April 1993 - (DCSO records Vol. 50 Page(s) 19018)

-----  
A point established as the ¼ sec. cor. of sec. 32 only by Boyer, Deputy County Surveyor, in 1939, and recorded in Douglas County Surveyor's Office file No. 16/25, perpetuated by James W. Byron, Deputy County Surveyor, in 1958, monumented with an iron post, 1½ ins. diam., firmly set, projecting 12 ins. above ground, with brass cap mkd. COUNTY SURVEYORS OFFICE T29S R8W SOUTH ¼ S32 T30S R8W 1958, from which bearing trees mkd. by Boyer:

An incense cedar, 62 ins. diam., bears S. 76¼° E., 39 lks. dist., no marks visible on rotted blaze.

A red cedar, 14 ins. diam., bears N. 10 ¾° W., 7 lks. dist., with healed blaze.

and the remains of a bearing tree mkd. by Byron

A root hole, bears West, 32 lks. dist., there is no remaining evidence of the tree.

It was determined that this position was established at midpoint between the cor. of secs. 4, 5, 32, and 33 and the cor. of secs. 5 and 6 only. This point will now function as the ¼ sec. cor. of sec. 5 only. The iron post was removed and the marks on the tree in sec. 32 were obliterated with concurrence from the Douglas County Surveyor.

(Cont. Next Page)

TOWNSHIP 29 RANGE 08 POINT IDENTIFIER # 241100

PRIMARY CORNER DESCRIPTION N. 1/4 Cor. for Sec. 5 only, T30-8

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

At the corner point  
Set a stainless steel post, 28 ins. long, 2½ ins. diam.,  
22 ins. in the ground, with brass cap mkd.

T29S R8W

¼ S5

T30S R8W

1993

from which new bearing trees

A fir, 17 ins. diam., bears S. 61° E., 32 lks. dist., mkd.  
¼ S5 BT.

A fir, 18 ins. diam., bears S. 22° W., 31 lks. dist., mkd.  
¼ S5 BT.

FD. & used on BLM resurvey by A. Bert Skeesick, Cadastral  
Surveyor under Group #1972, surveyed April/May 2001- (DCS0  
rec. Vol. 54 Page(s) 20962) (lies N.89°35'39 E., 45.10 ft. from  
the South ¼ Sec. 32 only, T29-8)