

PRIMARY CORNER DESCRIPTION Sec. Cor. for 16, 17, 20 and 21

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GL0 survey by Dennis Hathorn, Deputy Surveyor under Contract #57, dated April 12, 1855 - (DCSO records Vol. 16 Page(s) 6597)

Set post cor. secs. 16, 17, 20 and 21, from which
A Fir 24" dia., bears S.58°W., 33 lks. dist.
A Fir 12" dia., bears N.72°W., 47 lks. dist.
A Fir 36" dia., bears S.28°E., 42 lks. dist.
A Fir 5" dia., bears N.85°E., 33 lks. dist.

Douglas Co. Surveyors Office - James Byron, Deputy - Milo Godfrey; S. Bilow, crew - Sept./Oct. 1958 - C.S. File 49/100

Found - Orig. 5" now 14" Fir snag, N.85°E., 21.8 ft. This BT was rescribed about 20 years ago. I cut deeper and find orig. scribing "BT"
SE. and SW. BTs, now stumps, but show good scars.
I do not open.

Set Brass cap at cor. mkd: County Surveyors Office
T 29 S R 8 W
S 17 | S 16
S 20 | S 21
1958

New BTs- 12" W.Fir, S.76½°E., 30.6 ft. scribed S21 T29S R8W CS BT.
6" Yewwood, S.64°W., 35.2 ft. scribed CS S20 BT.
8" Yewwood, N.56½°W., 49.1 ft. scribed S17 T29S R8W CS BT.
5" Hemlock bears N.16°E., 98.0 ft. scribed S16 T29S R8W CS BT.

Douglas County Surveyors Office - Gary L. Langlitz, Deputy and crew - Dec. 2, 1975 - C.S. File 57/39-23

Found 1958 DCSO brass cap out of the ground. We find the following bearing trees: We find the three orig. BTs as noted in 1958. They occupy their record positions. We also find the following 1958 CS BTs:

12" now 18" W.Fir bears S.76½°E., 30.6 ft., alive and well healed.

6" now 8" Yew bears S.64°W., 35.2 ft. alive, with scribing visible on partially healed blaze.

8" now 11" yew bears N.56½°W., 49.1 ft., alive with scribing visible on partially healed blaze.

The NE. BT is down.

At the corner point as determined from the above mentioned bearing trees, WE RESET the 1958 County Surveyors brass cap.
(Cont. Next Page)

TOWNSHIP 29 RANGE 08 POINT IDENTIFIER # 300400

PRIMARY CORNER DESCRIPTION Sec. Cor. for 16, 17, 20 and 21

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

We add the markings "CS 1975" to the monument and mark the following new bearing tree:

6" D.Fir bears N.26°E., 14.6 ft. scribed "T29S R8W S16 CS BT" on a double blaze.

A 4" x 4" wooden post, painted white, is located approx. 1 ft. East of the corner.

The corner is located across a small draw at the SE. corner of the Camas Valley Disposal Site.

Fd. OK, Jan. 1995 by K. DeGroot - C.S. File 63/52 & M 121-33
Fd. Ok Feb. 2007 by Ken Hoffine - M152-41

Ron Quimby - Crew: N. Fromdahl, R. Heichel & R. Vincent -
10/2017 - C.S. File 65/99-24

Found - DCS0 brass cap (properly mkd)
24" Fir N.26°E., 14.6 ft. good scar.
28" W.Fir S.76°E., 30.6 ft. good scar.
12" Yew N.56°W., 49.1 ft. good scar.
36"x3' rotted stump S.28°E., 27.7 no visible blaze.
24"x3' rotted stump S.58°W., 21.8 no visible blaze.
New - 29" Fir S.58°W., 42.9 ft. scribed T29S R8W S20 BT.
Note - Corner is @ SE cor. of Camas Valley waste site.
Compass decl. 15½°E.

Fd as per record - D Edwards 11/2021 - M180-14