

PRIMARY CORNER DESCRIPTION Center 1/4 Cor. for Sec. 9

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

BLM resurvey by James E. Jelley and Wayne L. Rogers, Cadastral Surveyors, under Group #1027, surveyed May 1980/Aug. 1982 - (DCSO records Vol. 44 Page(s) 17010)

-----  
Point for the center 1/4 sec. cor. of sec. 9, at intersection with the E. and W. center line.

Set an iron post 28" long, 2½" dia., 24" in the ground with brass cap mkd:

T 29 S R 8 W  
C 1/4 S 9  
1980

from which

A Fir 10" dia., bears N.57 3/4°E., 37 lks. dist. mkd. C ¼ S9 BT.

A W. Fir 6" dia., bears S.7¼°W., 41 lks. dist. mkd. C ¼ S9 BT.

Fd. OK, Sept. 26, 1986 by OSHD - C.S. File 63/9-31

Douglas Co. Surveyors Office - Randall Smith and Stephen Flause, crew - March 30, 1990 - C.S. File 64/6-16

-----  
Found - 1980 BLM 3¼" dia., brass cap on a 2½" O.D. I.P. protruding 3" above ground.

10" now 12" dia., 19" high D.Fir stump with a fully healed blaze, bears N.57 3/4°E., 24.4 ft. (agrees w/rec)

6" now 10" dia. W.Fir with a fully healed single blaze, bears S.7¼°W., 27.1 ft. (agrees w/rec)

Set a 2 3/8" dia. brass cap on a 1 3/8" O.D. x 32" long I.P. is set East 100 ft. from BLM BC/IP. Cap stamped "Douglas County Surveyors T29S Sec 9 BO 1 West 100 ft. to C ¼ R8W 1990 Office" DSCO BC/IP protrudes 3" above ground.

(Bearings and distances from BO 1)

New BTs- 3" dia. D.Fir double blazed and scribed "X BT" bears S.7°W., 10.3 ft.

3" dia. D.Fir double blazed and scribed "X BT" bears N.61¼°E., 42.3 ft.

11" dia. Madrone barks scribed "BO C¼ S9 CS BT" bears N.80 3/4°E., 144.3 ft.

12" dia. Apple, did not blaze or scribe, bears S.14°E., 57.3 ft.

BLM BC/IP and BTs to C ¼ corner are to be destroyed by new highway construction.