

TOWNSHIP 29 RANGE 08 POINT IDENTIFIER # 340600

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 4 and 9

| | |
|-------------|-------------------|
| Alias _____ | Description _____ |
| Alias _____ | Description _____ |
| Alias _____ | Description _____ |
| Alias _____ | Description _____ |

GL0 survey by Dennis Hathorn, Deputy Surveyor under Contract #57, dated April 12, 1855 - (DCSO records Vol. 16 Page(s) 6599)

Set ¼ sec. post, from which
 An Oak 12" dia., bears S.40°W., 137 lks. dist.
 A Fir 18" dia., bears N.8°E., 164 lks. dist.

Set by C.W. Crocker of Oregon State Hwy.Dept. - Sept/Dec. 1939 - C.S. File 16/55

Set a 3/4" x 30" Iron bar from a 12" Oak, S.40°W., 1.37 chs. and this Oak was rotted down. Found old blazes but no scribe marks. Found 36" Fir scribe on bark, same original 18" Fir. Scribed following witness trees:
 A 36" Fir N.9°30'E., 1.64 chs. blazed and scribed CS BT. (Original)
 A 16" Fir S.10°W., 66 ft. blazed and scribed. New tree.

Douglas Co. Surveyors Office - James Byron, Deputy - Milo Godfrey; S. Bilow, crew - Sept. 1958 - C.S. File 49/100-29

Found both BTs and rod at corner as recorded by Boyer.
 NE. BT, now stump, shows barks scribing.
 SW. BT, also shows bark scribing "¼ S9".
New BT - 10" R.Fir bears N.56°W., 21.4 ft. scribed ¼ S4 CS BT.

Fd. OK, June 1980 by R. Hendrick - M 84-19

BLM resurvey by James E. Jelley and Wayne L. Rogers, Cadastral Surveyors, under Group #1027, surveyed May 1980/Aug. 1982 - (DCSO records Vol. 44 Page(s) 17006)

The ¼ sec. cor., perpetuated and recorded by Boyer in 1939, and further perpetuated and recorded by Byron in 1958, monumented with an iron rod, 3/4" dia., firmly set, projecting 4" above ground, from which the remains of an original bearing tree
 A sawed Fir stump 45" dia., bears N.8°E., 164 lks. dist., with fragmentary scribe marks visible on bark blaze.
and a bearing tree mkd. by Boyer
 A Fir 14" dia., bears S.10°W., 100 lks. dist., with healed blaze.
and a bearing tree mkd. by Byron
 A sawed Fir stump 10" dia., bears N.56°W., 32½ lks. dist., with fragmentary scribe marks visible on opened blaze.
(Cont. Next Page)

TOWNSHIP 29 RANGE 08 POINT IDENTIFIER # 340600

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 4 and 9

| | |
|-------------|-------------------|
| Alias _____ | Description _____ |
| Alias _____ | Description _____ |
| Alias _____ | Description _____ |
| Alias _____ | Description _____ |

At the corner point
Set an iron post, 28" long, 2 1/2" dia., 24" in the ground,
with brass cap mkd:

T 29 S R 8 W
1/4 $\frac{S 4}{S 9}$
1980

from which new bearing trees:

A W.Fir 8" dia., bears N.22½°E., 65 lks. dist. mkd. ¼ S4
BT.

A W.Fir 12" dia., bears S.65½°W., 71 lks. dist. mkd. ¼ S9
BT.

Deposit the iron rod alongside the iron post.

Fd. OK, May 1993 by L. Jay - M 117-22

David Edwards - For: Seneca Jones Timber Co. & Roseburg
Resources Co - 4/2008 - M155-31

Found - Brass cap
24" Fir, N.22½°E., 42.9'
16" Fir, S.65½°W., 46.9'
Both with healed blaze.