

TOWNSHIP 29 RANGE 08 POINT IDENTIFIER # 340700

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Sec. 4; & 33, T28-8

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GL0 survey by Dennis Hathorn, Deputy Surveyor under Contract #57, dated April 12, 1855 - (DCSO records Vol. 14 Page(s) 5794)

-----  
Set ¼ sec. post, from which  
    A Fir 40" dia., bears S.65°W., 30 lks. dist.  
    A Fir 40" dia., bears N.40°E., 4 lks. dist.

Douglas Co. Surveyors Office - James Byron, Deputy - Milo Godfrey; S. Bilow, crew - Sept. 17, 1957 - C.S. File 49/5-19

-----  
Found - Fir tree, now 48" dia., N.40°E., 2.6 ft., showing bark scribe "¼S". Very plain and scar of lower blaze.

    Fir stump, now 48" dia., S.65°W., 19.8 ft. Chop out blaze and find scribe mark "B". Did not chop out low enough to find more.

Distances are from face of old blazes.

Set Brass cap at cor. mkd: County Surveyors Office

    S 33      ¼      T28S  
    S 4           T29S

1957

NE tree in very good condition.

Mark one new tree:

    10" Red Cedar bears S.38°E., 37.1 ft., scribed T29S  
    R8W ¼ S4 CS BT.

Corner lies in bottom of gulch approx. 40 ft. West of small creek.

Douglas Co. Surveyors Office - John M. Powell, and crew - Aug. 21, 1969 - C.S. File 54/38-23

-----  
Found - 1957 DCSO brass cap which was pulled out when NE. BT fell.

    48" D.Fir, now down, N.40°E., 2.6 ft., bark scribe visible.

    48" D.Fir stump S.65°W., 19.8 ft. "B" visible.

    10" now 12" R.Cedar S.38°E., 37.1 ft., scribe visible.

Reset Brass cap at ¼ corner which was properly mkd. in 1957.

New BT - 12" R.Fir N.50°W., 11.0 ft. mkd. ¼ S33 CS BT.

Corner lies about 40 ft. West of small creek.

Fd. BC & 2 BTs by David Edwards - 4/2008 - M155-31, Set 6' steel post 2' south

FD. as per M155-31 by D. Edwards, 7/2011