

TOWNSHIP 29 RANGE 08 POINT IDENTIFIER # 400340

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 21 and 22

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

GL0 survey by Dennis Hathorn, Deputy Surveyor under Contract #57, dated April 12, 1855 - (DCSO records Vol. 16 Page(s) 6592)

-----  
Set ¼ sec. post, from which  
A Fir 18" dia., bears N.25°E., 17 lks. dist.  
A Chinquapin 12" dia., bears S.46°W., 22 lks. dist.

A. Boyer, Surveyor - Wit: C. McCann; Lewis Morris - Aug. 25, 1936 - C.S. File 23/56

-----  
Chinquapin BT to SW. dead and fallen down.  
Set 3" x 3" sq. post for corner from original, an 18" Fir to the NE. and blazed a 40" Fir and scribed it for BT in section 21, N.40°W., 36.5 ft. from ¼ corner.

Douglas Co. Surveyors Office - James Byron, Deputy - Milo Godfrey; S. Bilow, crew - Oct. 8, 1958 - C.S. File 49/100-39

-----  
Found - Orig. 18" now 36" stump, previously opened, shows good scribe "¼" N.25°E., 11.2 ft.  
Orig. 12" now 18", down and partly rotted Chinquapin, shows rotted face, checks for bearing and distance for orig. SW. BT.  
Boyer's 40" now stump, N.40°W., 36.5 ft., shows bark scribing.

Set Brass cap at cor. mkd: County Surveyors Office  
T 29 S R 8 W  
¼ S21 | S22  
1958

New BTs- 10" R.Fir, S.57°W., 33.8 ft. scribed ¼ S21 CS BT.  
12" Cedar, N.59°E., 21.0 ft. scribed ¼ S22 CS BT.

Douglas Co. Surveyors Office - Larry E. Monrean, Deputy - Randall Smith and Stephen Flause, crew - March 6, 1986 - C.S. File 62/34-4

-----  
Found - 1" x 36" I.P. with attached DCSO brass cap, properly marked. Cap has been pushed over apparently during fire trail construction. This monument is still in good condition. We use the position of the base of the monument as the corner location perpetuated by Byron. From this position, a wooden hub and tack, bears N.60°W., 1.0 ft.

Original monument not found. From the point used as 1958 perpetuation, references are tied as follows:  
(Cont. Next Page)

TOWNSHIP 29 RANGE 08 POINT IDENTIFIER # 400340

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 21 and 22

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

Orig. BT, an 18" Fir now a 30" DBH stump 5 ft. tall with scribing "¼S" visible on previously opened blaze, bears N.25°E., 12.7 ft. to center, 11.6 ft. to face. (Rec. N.25°E., 11.2 ft.) Blaze on S.54°W. side of stump.

A 40" Fir now a stump 36" dia. 2½ ft. tall bark scribed "S BT" bears N.40°W., 38.4 ft., 36.9 ft. to face. (Rec. 36.5 ft) Blaze on S.5°E., side of stump

A 10" now 20" Fir with well healed double blaze bears S.58°W., 33.8 ft. (Rec. S.57°W.) Blaze on N.26°E. side of tree.

A 12" now 19" Cedar with well healed double blaze, bears N.57½°E., 20.8 ft. (Rec. N.58°E., 21.0 ft.)

At position as previously described, WE RESET the found monument in an upright position. We add the marks "RESET 1986" to cap.

New BT - A 6" dia. Pine, double blazed and scribed "X BT", bears N.39°W., 28.9 ft.

Located in E-W cutting line. Area to South harvested.

---

Fd. OK, Jan. 1995 by K. DeGroot - M 121-33; C.S. File 63/52  
FD. Ok by Ken Hoffine - Sept. 2006 - M151-47

---

Brent Knapp, i.e. engineering - Crew: N. Fromdahl, J. Ogden, and L. Heddens - 11/2022 - C.S. File 65/111-27

-----

Found - DCS0 brass cap (properly mkd)  
Rotten 30"x5' Fir snag, N.25°E., 12.7'  
Rotten 36" Fir stump, N.40°W., 38.4'  
27" Fir, S.58°W., 33.8', blazed tag on North side of tree.  
20"x7' Cedar snag with slanted sawed top, N.57°E, 20.8', healed double blaze.  
9"x5' Pine snag, rotten, N.39°W., 28.9'

New - 14" Fir, N.79°E., 18.8', scribed "¼ S22 BT"  
13" Pine, S.40°E., 8.4', scribed "¼ S22 BT"

Note - Set post, 5.0' North.  
Compass Declination 15°E

---

2