

TOWNSHIP 29 RANGE 08 POINT IDENTIFIER # 500640

PRIMARY CORNER DESCRIPTION 1/4 cor. for Secs. 2 and 3

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GL0 survey by Dennis Hathorn, Deputy Surveyor under Contract #57, dated April 12, 1855 - (DCSO records Vol. 16 Page(s) 6589)

-----  
Set ¼ sec. post, from which  
A Fir 36" dia., bears N.55°W., 43 lks. dist.  
A Fir 36" dia., bears S.55°E., 52 lks. dist.

Douglas Co. Surveyors Office - James Byron, Deputy - Milo Godfrey; S. Bilow, crew - Sept. 1958 - C.S. File 49/100-29

-----  
Found - Orig. 36", should have been 24", now 36" Fir stump, N.55°W., 28.4 ft. I open and find good scribing "B", checks for ring count.  
Traces of rotted stump that checks bearing and distance for SE. BT.

Set Brass cap at cor. mkd: County Surveyors Office  
T 29 S R 8 W  
¼ S3|S2  
1958

New BTs- 8" Cedar bears S.62°E., 11.2 ft. scribed ¼ S2 CS BT  
12" R.Fir bears N.24°W., 70.5 ft. scribed ¼ S3 CSBT

Fd. Ok - G Baughman - March 1977 - M65-8 (info added 3/2002)

Gary Smithers - For: Seneca Jones Timber Co - 4/2002 - M140-3

-----  
Found - 1958 Douglas Co. iron pipe w/brass cap with steel fence post, per C.S. File 49/100  
36" rotted Fir stump N.55°W., 28.4 ft. with visible scribe "B" with old tag.  
15" Cedar S.62°E., 11.2 ft. with healed face & old tag.  
21" D.Fir N.24°W., 70.5 ft. with healed face & old tag.

New BTs- 12" Cedar S.61°W., 14.9 ft. to spike set side center, scribed "T29 R8 ¼ S3 BT" with tag.  
21" D.Fir N.23°E., 13.3 ft. to spike set side center, scribed "T29 R8 ¼ S2 BT" with tag.