

TOWNSHIP 29 RANGE 08 POINT IDENTIFIER # 600300

PRIMARY CORNER DESCRIPTION Sec. Cor. for 23, 24, 25 and 26

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GL0 survey by Dennis Hathorn, Deputy Surveyor under Contract #57, dated April 12, 1855 - (DCSO records Vol. 16 Pg 6580)

Set post cor. secs. 23, 24, 25 and 26, from which
A Laurel 4" dia., bears N.35°E., 15 lks. dist.
A Laurel 12" dia., bears S.67°W., 50 lks. dist.
An Oak 12" dia., bears S.30°E., 109 lks. dist.
A Fir 6" dia., bears N.85°W., 139 lks. dist.

Orig. (Corrective resurvey)- Fred Mensch, U.S. Deputy Surveyor - under date of April 18, 1924 - (DCSO records Vol. 14 Page(s) 6025-26)

Intersect the point for cor. of secs. 23, 24, 25 and 26, located by measurement from the original bearing trees.

At the exact cor. point

Set an iron post, 3 ft. long, 2" dia., 28" in the ground, for cor. of secs. , with brass cap marked

T29S:R8W

S23:S24

S26:S25

1924

from which the original bearing trees:

A B.Oak 14" dia., bears S.26°E., 89 lks. (not S.30°E., 109 lks.) marks are plain.

A Laurel, rotted down, bears S.67°W., 50 lks., stump shows position.

A Fir 24" dia., bears N.89°W., 139 lks. (Not N.85°W.) marks are plain on the bark.

No evidence of NE. bearing tree.

New Bearing trees:

A Fir 18" dia., bears N.33°E., 49 lks mkd. T29S R8W S24 BT

A Fir 18" dia., bears S.5°E., 54 lks mkd. T29S R8W S25 BT.

A Fir 18" dia., bears S.35°W., 32 lks mkd. T29S R8W S26 BT

A Fir 18" dia., bears N.65°W., 51 lks mkd. T29S R8W S23 BT

Survey by Howard W. Johnstone, LS #498 - For: Roseburg Lumber Co. - Dec. 29, 1981 - C.S. File 58/229-8

Found - 1924 Cadastral brass cap, in good condition.

18" Fir, N.33°E., 32.3 ft. O.B.T.

18" Fir S.15°E., 35.6 ft. (Rec. S.5°E.) O.B.T., in good condition.

18" Fir S.35°W., 21.1 ft. O.B.T., good condition.

18" Fir N.65°W., 33.7 ft., O.B.T., now a stump in a clearcut of the SE. corner of sec. 23.

Set 5/8" x 30" I.R. rebar with alum. cap mkd. "L.S. 498" at base of O.B.T. stump N.65°W., 33.3 ft. _____ cont.

Alias	Description

Survey by Howard W. Johnstone, LS #498 - For: Roseburg Lumber Co. - March 1990 - M 101-76

CORNER REPORT ONLY

Found - 1924 Cad. brass cap.
18" Fir N.33°E., 32.3 ft., stump.
24" Fir S.5°E., 35.6 ft., healed. (1981 visit calls out S.15°E. with record being S.5°E.)
5/8" Iron rod and alum. cap N.65°W., 33.3 ft.
24" Fir S.35°W., 21.1 ft., healed.

Daniel Saily, Lone Rock Timber Management Co. - Crew: Brett Ragon & Ignacio Roman - 12/20/2022 - C.S. File 65/111-31

Found - 1924 GLO BRASS CAP
27"x1 ft tall rotten D.Fir stump bears N.32¾°E., 31.9 ft (rec N.33°E. 32.3 ft) No tag, healed face
31" D.Fir bears S.14½°E., 35.9 ft (rec S.5°E., (S.15°E.) 35.6 ft). Douglas County tag and well healed face.
27" D.Fir bears S.36°W., 20.8 ft (rec S.35°W., 21.1 ft). Steel tag and well healed face
5/8" iron rod with aluminum cap mkd: LS 498 bears N.63°13'22"W., 32.21 ft (record N.65°W., 33.3). We find the iron rod loose and leaning slightly to the East. We straighten and drive the rod down until tight. Top of rod is approx. 1 ft above ground level

New - 13" D.Fir bears N.39¾°E., 32.1 ft. We scribe T29S R8W S24 BT and tag tree.
We place a 5½ ft tall galvanized steel U-Post North 1.0 ft.

Note - Fd 1924 General Land Office brass cap & iron pipe, top of corner monument is 0.7 ft above ground level. Monument lies on steep South slope approx. 500 ft North of main rock road in heavy timber. We ran a random closed loop traverse from the sec. corner of sections 23, 24, 25 and 26 to the East 1/16th corner of sections 23 and 26 and rotated to Johnstone's bearing from M101-76. Distances to BTs were measured using a TRIMBLE C5 TOTAL STATION to an aluminum nail at the side center. The new BT was scribed at the root collar and the face was painted with red paint.

Bearing Basis - Johnstone's survey M101-76, which is based on 1924 Cadastral survey.