

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 13 and 14

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by Dennis Hathorn, Deputy Surveyor under Contract #57, dated April 12, 1855 - (DCSO records Vol. 16 Page(s) 6582)

Set ¼ sec. post, from which
A Fir 24" dia., bears S.12°W., 65 lks. dist.
A Chinquapin 5" dia., bears S.66°E., 22 lks. dist.

(Corrective resurvey)- Fred Mensch, U.S. Deputy Surveyor - under date of April 18, 1924 - (DCSO records Vol. 14 Page(s) 6030)

Intersect the point for the ¼ sec. cor., located by measurement from the original bearing trees.

At the exact cor. point
Set a iron post 3 ft. long, 1" dia., 28" in the ground, for ¼ sec. cor. with brass cap mkd:

¼
S14:S13
1924

from which the original bearing trees:
A Chinquapin stump, bears S.66°E., 22 lks. dist.
A Fir 30" dia., bears S.12°W., 65 lks. dist., marks are plain on the bark.

New bearing trees:
A Fir 16" dia., bears N.89°E., 9 lks. dist. mkd. ¼ S13 BT.
A Fir 22" dia., bears N.34°W., 21 lks. dist. mkd. ¼ S14 BT

Douglas Co. Surveyors Office - John M. Powell, and crew - Nov/Dec. 1966 - C.S. File 54/38-8

Found - GLO brass cap, properly mkd. in 1924, but out of ground.

Orig. 30" now 37" D.Fir S.12°W., 42.9 ft., bark scribed "¼S"

16" D.Fir, now snag, N.89°E., 5.9 ft., opened for scribe "¼ 13".

22" now 27" D.Fir, N.34°W., 13.9 ft., shows good scar.

Reset brass cap using all bearing and distances to BTs.

New BT - 7" D.Fir S.55°E., 38.4 ft. mkd. ¼ S13 CS BT.

Fd. and used in BLM resurvey by Charles E. Akin, Jr.; James E. Jelley, Cadastral Surveyors and Bruce A. Shaner, RLS #430, under Contract #52500-CT5-1117 - Surveyed June 1973/April 1976 Under Group #'s808; 858; 860, - (DCSO records Vol. 39 Page(s) 15758-59)

(Cont. Next Page)

TOWNSHIP 29 RANGE 08 POINT IDENTIFIER # 600440

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 13 and 14

Alias	_____	Description	_____
Alias	_____	Description	_____
Alias	_____	Description	_____
Alias	_____	Description	_____

Douglas County Surveyors Office - Larry Monrean; Karen Cheney, crew - May 2, 1977 - C.S. File 59/34-3

CORNER REPORT ONLY

Found a 1" dia. iron pipe with brass cap attached mkd. in 1924. Monument firmly set 4" high, from which

Orig. 30" now 38" D.Fir S.12°W., 42.9 ft., barks scribe "¼S"

1924 BT, 16" D.Fir snag, N.86°E. (Rec. N.89°E.) 5.6 ft. (Rec. 5.9 ft.), previously chopped for scribe "¼ S13".

1966 BT, 7" now 9" D.Fir S.52°E., (Rec. S.55°E.) 38.4 ft., partially healed over blaze, no scribing visible.

22" now 28" D.Fir N.34°W., 13.9 ft., good scar.

Orig. 5" Chinquapin S.66°E., 22 lks. (14.5 ft.), not found. (Gone)

Corner is on a steep easterly slope at the SW. corner of an old clear cut.