

PRIMARY CORNER DESCRIPTION Center 1/4 Cor. for Sec. 13

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

A. Boyer - For: Mrs. A.W. Kearby - Aug. 1970 - M 39-79A

(Monument set ??), from which
10" R.Fir S.32°E., 19.7 ft.
40" R.Fir N.52°30'E., 57.5 ft.

Survey by Bruce Shaner - For: Bureau of Land Management -
Nov. 26, 1975 - C.S. File 58/82 and M 58-76 (also filed with
BLM records, DCSO Vol. 39 Page 15778)

Set Iron post 28" long, 2¼" dia., 20" in ground with brass
cap mkd: T29S R8W W.M. C 1/4 S13 1975,
from which
A Fir 12" bears N.15°W., 27 lks. mkd. C¼ S13 BT.
A Fir 12" bears S.25°W., 129 lks. mkd. C¼ S13 BT.

Douglas Co. Surveyors Office - L.E. Monrean; R.B. Kimberling;
K.Cheney; S.J. Flause, crew - May 2, 1977 - C.S. File 59/34-2

CONDITION REPORT ONLY

Found Shaner 1975 Iron pipe 2¼" dia., 8" high with brass cap
attached mkd. "T29S R8W WM C¼+S13 1975", then S.17°W., 49.4
ft. to Boyer monument, a 3/4" dia. iron bar at C¼ as
determined by Boyer per his map M 39-79A.

From Shaner's monument:

A Fir 12" now 11" dia., bears N.12½°W., 18.1 ft. (Rec.
N.15°W., 17.8 ft.) Tree blazed with scribing visible
"C¼ S13 BT"

A Fir 12" dia., bears S.26½°W., 85.1 ft. (Rec. S.25°W.)
Tree blazed with scribing visible "13 BT"

BTs from Boyer's monument:

Red Fir 40" now 48" dia., bears N.57°E., 57.5 ft. (Rec.
N.52°30'E) Tree has well healed blaze.

Red Fir 10" now 13" dia., bears S.32°E., 19.7 ft. to face,
20.7 ft. to center at base.

David Edwards - For: Roseburg Resources - 2/6/2003 - M141-55

Found - BLM brass cap
17" Fir S.25°W., 85.1'

New BT - 11" Fir S.81°E., 13.8'

Set - 6' steel posts w/tags 5.00' north & 5.00' West.