

TOWNSHIP 29 RANGE 08 POINT IDENTIFIER # 673100

PRIMARY CORNER DESCRIPTION NE Cor. Sec. 1, T30-8

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

GLO survey by W.H. Byars, Deputy Surveyor under contract # 450 dated July 28, 1882 (DCSO records Vol. 17 Page(s) 7255)

-----  
Set a Fir post at the point of intersection (7.08 chs. West of the SW cor. Sec. 31, T29½S R7W) 4 ft. long, 4" 3 sq. (triangular) for the cor. to secs. 1 and 6 marked T29S R8W S36 on N. side; T30S R7W S6 on SE. face; R7W S1 C C on the SW. face; and from which

A Cedar 22" dia., bears N.27°E., 47 lks. dist. mkd. T29S R8W S36 BT.

A Cedar 24" dia., bears S.56°E., 19 lks. dit. mkd. T30S R7W S6 BT.

A Fir 10" dia., bears S.80°W., 18 lks. dist. mkd. T30S R8W S1 BT.

Douglas County Surveyors Office - James W. Byron, Deputy - Dale McFarland; John Powell, crew - June 1962 - C.S. File 49/139-81

-----  
Found Cedar S.56°E., 17.5 ft. and Cedar N.27°E., 31.0 ft. Both trees had been previously opened. Found old axe work on SE. tree but scribing had rotted. Evidence of corner being used. Corner also checks bearing and distance from 36, 31 and 6 (7.08 chs.)

Set brass cap at cor. mkd: County Surveyors office

T29S  
R8W   S36   R7W  
      S1|S6 T30S  
      1962

Rescribed old BT, 36" Cedar S.56°E., 12.5 ft. "T30S R7W S6 CS BT."

New BTs -14" Hemlock N.1°E., 10.7 ft. "T29S R8W S36 CS BT"

14" Cedar S.71½°W., 21. ft. "T30S R8W S1 CS BT".

Mark Smalley - For: Roseburg Resources - 10/06/2006 - C.S. File 65/58-24

-----  
Found - 1962 DCSO IPBC (properly mkd)  
43" Cedar S.56°E., 12.5 center rooted away - axe work visible.

14" hemlock N.1°E., 10.7 down rotted face.

23" cedar S.71½°W., 21.0 good healed face.

New - 22" cedar N.73°W., 46.8 scribed "S6 BT"

10" fir N.22°E., 20.4 scribed "S6 BT"

Compass decl. 16½°E.