

TOWNSHIP 29 RANGE 09 POINT IDENTIFIER # 400200

PRIMARY CORNER DESCRIPTION Sec. Cor. for 27, 28, 33 and 34

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

GL0 survey by Dennis Hathorn, Deputy Surveyor under Contract #57, dated April 12, 1855 - (DCSO records Vol. 16 Page(s) 6627-28)

-----  
Set post cor. of secs. 27, 28, 33 and 34, from which  
A Fir 12" dia., bears S.70°E., 175 lks.  
A Fir 24" dia., bears N.78°W., 41 lks.  
A Fir 15" dia., bears S.78°W., 52 lks.  
A Hemlock 12" dia., bears N.3°E., 117 lks.

GL0 resurvey by William M. Porter, Deputy Surveyor, Under Special Instructions dated June 5, 1907, Independent of, but in connection with his contract #768, dated March 8, 1907 - (DCSO records Vol. 16 Page(s) 6634)

-----  
Post and witness trees gone. Set a Fir post 3 ft. long, 4" sq., 24" in ground for sec. cor., marked T29S S27 on NE.; R9W S34 on SE.; S33 on SW.; and S28 on NW. faces, with 1 notch on S. and 3 notches on E. edges, from which  
A Maple 10" dia., bears N.80°E., 21 lks. dist. mkd. T29S R9W S27 BT.  
A Fir 6" dia., (old BT) bears S.70°E., 175 lks. mkd. T29S R9W S34 BT.  
An Alder 12" dia., bears S.15°W., 30 lks. mkd. T29S R9W S33 BT.  
A Fir 30" dia., (old BT) bears N.78°W., 41 lks. m kd. T29S R9W S28 BT.

Douglas Co. Surveyors Office - James Byron, Deputy - Milo Godfrey; J. Fee, crew - July 16, 1957 - C.S. File 49/7-2

-----  
Found all four BTs as recorded by Porter in 1907, all check for bearings except NW. BT, should be N.68°W. All check for distances.

The NW. BT now 48" Fir stump, only bark scribed.  
The SW. BT now 15" dead Alder, open and good scribing.  
The NE. BT grown over. I do not open.  
The SE. BT now 36" Fir, dead snag shows good bark scribing.

Also find 24x4x4 in. Fir stake scribed for corner, bears N.70°W., 2.0 ft. from corner.

Set Brass cap at cor. mkd: County Surveyors Office  
C T 29 S R 9 W D  
0 S 28 | S 27 0  
0 S 33 | S 34 U  
S 1957 G

from which  
(Cont. Next Page)

TOWNSHIP 29 RANGE 09 POINT IDENTIFIER # 400200

PRIMARY CORNER DESCRIPTION Sec. Cor. for 27, 28, 33 and 34

Alias	Description
_____	_____
_____	_____
_____	_____
_____	_____

10" Hemlock bears S.57°E., 38.5 ft. S34 T29S R9W CS BT  
14" Maple bears S.56°W., 23.3 ft. S33 T29S R9W CS BT.  
15" W.Fir bears N.54°W., 54.6 ft. S28 T29S R9W CS BT.

Fd. and used in survey by Russell Torbeck, Coos County -  
April 1991 (See DCSO records, M 113-20)

Douglas Co. Surveyors Office - Larry E. Monrean, Deputy;  
Randall Smith, crew - June 3, 1991 - C.S. File 64/15-9

-----  
Found - Orig. post not found. Found a 2" x 3" x 2 ft post  
with faint scribe marks lying loose on top of  
ground.  
1957 Byron monument, a 1" x 36" I.P with brass cap  
properly mkd., is leaning northeasterly.  
Find and use a wooden hub located at the probable  
plumb position of monument to measure to  
accessories found.  
Orig. 24" Fir now a 5 ft. dia. decayed stump with  
fragmentary reverse scribing in previously open  
blaze, bears N.66½°W., 27.5 ft. (Rec. N.78°W.,  
27.1 ft.)  
Orig. 12" Fir now a 36" dia. stump approx. 10 ft.  
high with bark scribing "29S R9W 3" visible and  
well healed lower blaze, bears S.73°E. 114.1 ft  
1907 BT, 10" now 20" Maple with well healed single  
blaze, bears N.57½°E., 15.6 ft. (Rec. N.80°E.,  
13.9 ft.)  
1957 BT, 10" now 20" Hemlock with well healed  
single blaze, bears S.59°E., 38.5 ft. (Rec.  
S.57°E.)  
1957 BT, 14" now 20" Maple with well healed single  
blaze, bears S.54½°W., 24.0 ft.  
1957 BT, 15" now 37" Fir with well healed single  
blaze, bears N.53p°W., 54.3 ft. (Rec. N.54°W.  
54.6 ft.)

All measurements taken to estimated center of root crown of  
BTs.

We remove Byron's cap monument and SET a 5/8" x 30" iron  
rod with alum. cap at plumb position of monument (as mkd.  
by wooden hub). Alum. cap is mkd. "Douglas Co. Surveyor"  
We RESET the brass cap monument at location agreeing with  
orig. bearings and distances to orig. BTs. Monument is set  
with 7" above ground. We stamp the additional wording  
"RESET 1991" on cap. From this monument, the old location  
as mkd. by iron rod and alum. cap bears S.17½°W., 5.66 ft.  
New Accessories:

(Cont. Next Page)

TOWNSHIP 29 RANGE 09 POINT IDENTIFIER # 400200

PRIMARY CORNER DESCRIPTION Sec. Cor. for 27, 28, 33 and 34

Alias	Description
_____	_____
Alias	Description
_____	_____
Alias	Description
_____	_____
Alias	Description
_____	_____

Orig. 5 ft. dia. stump bears N.78°W., 27.1 ft.  
Orig. 36" Fir stump bears S.70°E., 115.5 ft.  
1907 resurvey 20" Maple bears N.75°E., 11.8 ft.  
Byron's 1957 20" Hemlock bears S.51½°E., 40.4 ft.  
Byron's 1957 20" Maple bears S.50°W., 27.6 ft.  
Byron's 1957 37" Fir bears N.59½°W., 52.4 ft.  
(Sketch in C.S. File)

Kris DeGroot - For Silver Butte Timber - 6/2010 - M160-78  
-----  
Found 1959/1991 DCSO BCIP & accessories per (Ren)  
Lat: 43°00'39.080003"N Long. 123°45'41.695029"W

BLM retracement by George M. Winter, Cadastral Surveyor, under Group No. 2500, OR Admin file No. 1302, surveyed March/May 2013 - (DCSO Records BLM Plat T29-9 2014-1)  
-----  
The cor. of secs. 27, 28, 33, and 34, perpetuated by the Douglas County Surveyor's Office in 1957 and 1991, monumented with on iron post, 1½" dia., firmly set, projecting 11" above ground, with a wooden post set alongside the southeast side, and brass cap (properly)mkd.  
from which the remains of the original bearing trees  
A decayed fir stump, size indeterminate, bears S.70°E., 115.5 ft. with no marks visible.  
A decayed fir stump, 60" dia., bears N.78°W., 27.1 ft., with no marks visible  
and bearing tree mkd. by Porter in 1909  
A maple, 24" dia., bears S.78°E., 11.9 ft., with a healed blaze. (Record, N.80°E., 13.9 ft.)  
and the remains of BTs mkd. by the Douglas County Surveyor's Office in 1957  
A decayed hemlock stump, 24" dia., bears S.52¼°E., 40.0 ft., with a hollowed blaze.  
A maple, 25" dia., bears S.46¼°W., 26.2 ft., with a healed blaze.  
A fir, 48" dia., bears N.60°W., 52.7 ft., with a healed blaze.  
and a new bearing tree  
A fir, 8" dia.. bears N.45½°E., 48.8 ft., mkd. T29S R9W S27 BT.  
Corner is located alongside the south side of a skid road, bears E. and W.

continued next page

PRIMARY CORNER DESCRIPTION Sec. Cor. for 27, 28, 33 and 34

Alias	Description
_____	_____
_____	_____
_____	_____
_____	_____

BLM Dependent resurvey by Joseph J Johnson, Cadastral Surveyor under Group #2864, surveyed Feb. 2017/Oct. 2018 - (DCSO Records Vol. 59 Page(s) 23695-6)

-----  
The cor. of secs. 27, 28, 33, & 34, monumented with an iron post, 1½" dia., firmly set, projecting 12" above ground, with a brass cap (properly) mkd.

from which the remains of the original bearing trees

A decayed fir stump, size indeterminate, bears S.70°E., 115.5 ft., no marks visible.

A decayed fir stump, 72" dia., bears N.78°W., 27.1 ft., no marks visible.

and a BT mkd. by Porter in 1909, reported by Winter in 2013

A maple, 27" dia., bears S.78°E., 11.9 ft., with a healed blaze.

and the remains of a BT mkd. by Byron, in 1957, reported by Winter in 2013

A decayed hemlock stump, 25" dia., bears S.52¼°E., 40.0 ft., with a healed blaze.

A maple, 26" dia., bears S.46¼°W 26.2 ft. with a healed blaze.

A fir stump, 55" dia., bears N.60°W., 52.7 ft., with a healed blaze.

and a bearing tree mkd. by Winter in 2013

A fir, 9" dia., bears N.45½°E., 48.8 ft., with scribe marks T29S R9W S27 BT visible on partially healed blaze.

and a new reference monument

An iron rod, 30" long, 5/8" dia., set 28" in the ground for a reference monument bears N.45°11'15"W., 24.09 ft. with aluminum cap mkd. RM S28 24.1 FT TO COR T29S R9W 2017 and an arrow pointing to the cor.

From this cor., a point established by Byron, Douglas County Deputy Surveyor, in July 1957, redesignated and perpetuated by Monrean, in 1991, and was not utilized in the course of this survey, bears S.10°57'47"W., 5.40 ft. monumented with an iron rod, 5/8" dia., firmly set, projecting 1" above ground, with an aluminum cap mkd. DOUGLAS CO SURVEYOR.

NAD 1983 (2011)

Latitude: 43°00'39.08"N. Longitude: 123°45'41.70"W.