

TOWNSHIP 29 RANGE 09 POINT IDENTIFIER # 400240

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 27 and 28

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by Dennis Hathorn, Deputy Surveyor under Contract #57, dated April 12, 1855 - (DCSO records Vol. 16 Page(s) 6628)

Set ¼ sec. post, from which
A Laurel 10" dia., bears N.7°E., 46 lks.
A Fir 12" dia., bears S.45°W., 5 lks.

GLO resurvey by William M. Porter, Deputy Surveyor, Under Special Instructions dated June 5, 1907, Independent of, but in connection with his contract #768, dated March 8, 1907 - (DCSO records Vol. 16 Page(s) 6635)

Intersect at point for ¼ sec. cor. Post and 1 witness tree destroyed. Set a basalt 12x9x6 ins., 8" in ground marked ¼ on W. face, from which
A Laurel 10" dia., bears N.85°E., 35 lks. dist. mkd. ¼ S27 BT.
A Fir (old BT) 16" dia., bears S.45°W., 5 lks. mkd. ¼ S28 BT.

Douglas Co. Surveyors Office - James Byron, Deputy - Milo Godfrey; C. Putnam, crew - Oct. 1959 - C.S. File 49/100-71

Found - Sandstone rock 10" x 10" x 6" at corner with "¼" chiseled on West face.
Fir tree, now 44", bark scribed "¼" and showing fair lower scar 3.3 ft. West of corner.
Rotted remnants of Laurel stump N.85°E., approx. 23 ft Too far gone to find scribing or even any sign of face.
At corner, SET Iron pipe with brass cap mkd:
Douglas County Surveyor Office
T 29 S R 9 W
¼ S 28 | S 27
1959
Blaze and scribe one new tree:
17" Fir S.35°E., 41.0 ft. mkd. ¼ S27 CS BT.

BLM resurvey by A. Bert Skeesick Cadastral Surveyor under Group #2043, surveyed May/June 2003 - (DCSO rec. Vol. 55 Page(s) 21360)

The ¼ sec. cor. of secs. 27 & 28, remonumented by the Douglas County Surveyor's Office in 1959, monumented with an iron post, 1¼" dia., firmly set, projecting 24" above ground, with brass cap (properly) mkd.
continued next page

TOWNSHIP 29 RANGE 09 POINT IDENTIFIER # 400240

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 27 and 28

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

from which the remains of an original bearing tree
A sawed fir stump, 48" dia., bears S.45°W., 3.3 ft., with
a healed blaze.
and the remains of a bearing tree mkd. by the Douglas County
Surveyor's Office
A sawed fir stump, 18" dia., bears S.35°E., 41.0 ft., with
a healed double blaze.
and new bearing trees
A fir, 6" dia., bears N.38°E., 24.5 ft., mkd. ¼ S27 BT.
A fir, 8" dia., bears S.1¾°W., 14.3 ft., mkd. ¼ S28 BT.
Each new bearing tree has a 2½"x ¼" magnetic nail (Mag Nail)
driven at the base right side-center, unless otherwise
described in the corner description

Kris DeGroot - For Silver Butte Timber - 6/2010 - M160-78

Found 1959 DCSO BCIP & accessories per (Ren)
Lat: 43°01'04.698273"N Long. 123°45'41.419498"W