

TOWNSHIP 29 RANGE 09 POINT IDENTIFIER # 440200

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 27 and 34

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GL0 survey by Dennis Hathorn, Deputy Surveyor under Contract #57, dated April 12, 1855 - (DCSO records Vol. 16 Page 6628)

Set 1/4 sec. post, from which
A Cedar 10" dia., bears N.58°W., 8 lks.
A Fir 10" dia., bears S.20°W., 23 lks.

Douglas Co. Surveyors Office - James Byron, Deputy - Milo Godfrey; C. Putnam, crew - Oct. 1959 - C.S. File 49/100-68

Found - Cedar tree, now 15", N.58°W., 5.3 ft. This tree has been opened previously and scribing "1/4S" can be plainly seen. Tree also has good lower scar.
Fir snag, now 13", S.26°W., instead of S.20°W., 15.2 ft. Bottom scar has been opened previously and shows good scribing "BT".

Set Brass cap at cor. mkd: County Surveyors Office
T 29 S R 9 W
1/4 S 27
S 34
1959

Blaze and scribe one new tree:
8" I.Cedar S.67°W., 29.4 ft. scribed 1/4 S34 CS BT.

Fd. OK, March 1996 by K. Hoffine - M 123-59

BLM resurvey by A. Bert Skeesick Cadastral Surveyor under Group #2043, surveyed May/June 2003 - (DCSO rec. Vol. 55 Page(s) 21358)

From the 1/4 sec. cor. of secs. 27 & 34, remonumented by the Douglas County Surveyor's Office in 1959, monumented with an iron post, 1 1/4" dia., firmly set, projecting 12" above ground, with brass cap (properly) mkd.

from which the remains of the original bearing trees
A root hole bears S.20°W., 15.2 ft., with fallen trunk, size indeterminate, lying alongside, with scribe marks BT visible on partially opened blaze.

A cedar, 21" dia., bears N.58°W., 5.3 ft., with no marks visible.

and a BT mkd. by the Douglas County Surveyor's Office
A cedar, 17" dia., bears S. 65 1/4° W., 29.4 ft. dist., with a healed double blaze.

Corner is located S.15°E., 3.2 ft., from a fence corner with woven wire fences extending N., E., and W.

continued next page

TOWNSHIP 29 RANGE 09 POINT IDENTIFIER # 440200

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 27 and 34

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

BLM retracement by George M. Winter, Cadastral Surveyor, under Group No. 2500, OR Admin file No. 1302, surveyed March/May 2013 - (DCSO Records BLM Plat T29-9 2014-1)

The ¼ sec. cor. of secs. 27 and 34, perpetuated by the Douglas County Surveyor's Office in 1959, monumented with an iron post, 1¼" dia., firmly set, projecting 12" above ground, with brass cap (properly) mkd.

from which the remains of the original BTs

A roothole bears S.20°W., 15.2 ft., with a fallen, decayed trunk, size indeterminate, laying alongside, with a slab of wood mkd. BT laying on top of the trunk.

A cedar, 22" dia., bears N.58°W., 5.3 ft., with axe marks visible.

and BT mkd. by the Douglas County Surveyors Office

A cedar, 17" dia., bears S.65¼°W., 29.4 ft., with a healed double blaze.

Corner is located 1 ft. south of a fence line, bears E and W, and 1 ft. E of the extension line of a fence line, bears N.

NAD 1983 (2011)

Latitude - 43°00'39.110"N. Longitude 123°45'05.907"W.