

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 15 and 22

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

GLO resurvey by William M. Porter, Deputy Surveyor, Under contract #768, dated March 8, 1907 - (DCSO records Vol. 16 Page(s) 6644)

-----  
Set Fir post 3 ft. long, 4" sq., 24" in ground for ¼ sec. cor. marked ¼ S15 on N.; and 22 on S. faces; from which  
A Maple 8" dia., bears North, 10 lks. mkd. ¼ S15 BT.  
A Fir 50" dia., bears S.80°E., 26 lks. mkd. ¼ S22 BT

Douglas Co. Surveyors Office - James Byron, Deputy - Milo Godfrey; C. Putnam, crew - Sept. 1959 - C.S. File 49/100-51

-----  
Found - Orig. 8" now 18" Maple, North 6.6 ft., shows old scars. I do not open.  
Orig. 50" now 56" Fir S.80°E., 17.2 ft. I open and find good scribing "S22".

Set Brass cap at cor. mkd: County Surveyors Office  
T 29 S R 9 W  
¼ S 15  
S 22  
1959

Corner on sandstone ledge, I excavate hole about 6" deep and concrete pipe in place.  
New BT - 18" Cedar bears S.55½°E., 42.7 ft. scribed ¼ S22 CS BT.

Douglas Co. Surveyors Office - Randall Smith and Stephen Flause, crew - Oct. 23, 1996 - C.S. File 65/9-30

-----  
Found - 2½" dia. brass cap on a 1½" O.D. iron pipe, concreted into a sandstone ledge. BC/IP protrudes 8".

Original Maple now gone.  
50" now 56" dia., 12 ft. high burnt D.Fir snag, shows evidence of being opened. No scribing visible, bears S.80°E., 17.2 ft. (agrees w/rec) O.B.T.

18" now 27" dia. Cedar with a fully healed double blaze, bears S.55½°E., 42.7 ft. (agrees w/rec)  
New BTs- 6" dia. D.Fir, double blazed and scribed "¼ S22 CS BT", bears S.30½°E., 36.6 ft.  
11" dia. Maple, double blazed and scribed "¼ S15 CS BT", bears N.73½°W., 25.4 ft.  
6" dia. Madrone, barks scribed "¼ S15 CS BT" bears N.69°E., 31.9 ft.

Corner lies on a steep southerly facing rock bluff.