

TOWNSHIP 29 RANGE 09 POINT IDENTIFIER # 440700

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Sec. 3; & 34, T28-9

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

ON THE COUNTY LINE - CHECK WITH COOS COUNTY
FOR POSSIBLY MORE INFORMATION

GL0 survey by Dennis Hathorn, Deputy Surveyor under Contract #57, dated April 12, 1855 - (DCSO records Vol. 16 Page 6616)

Set ¼ sec. post, from which
 A Fir 18" dia., bears N.45°W., 9 lks.
 A Fir 18" dia., bears S.81½°E., 8 lks.

GL0 survey by W. S. Chapman, Deputy Surveyor, under Contract #234, dated June 24, 1875 - (DCSO records Vol. 30 Page(s) 12843 and 12845)

(Page 12843)
After considerable search, being unable to find the ¼ post - reported as set - between secs. 3 and 34, from the post still standing.
(Page 12845)
Set post 4 ft. long, 4" dia., one ft. in ground, for ¼ sec. cor., from which
 An Alder 5" dia., bears South, 49 lks.
 A Fir 24" dia., bears N.10°W., 29 lks.

Douglas Co. Surveyors Office - James Byron, Deputy - Mike Darby; Wm. Stoffel, crew - June 20, 1963 - C.S. 49/100-82

Found - Stump of orig. now 30" Fir stump, N.10°W., 19.1 ft., shows good bark scribing "¼". We nail yellow tag near base.
Water falls bears N.55°E., 1200 ft. Corner is on top of spur.
Set Brass cap at cor. mkd: County Surveyors Office
 ¼ S 34 T28S
 S 3 T29S R9W
 1963
New BT - 62" Cedar bears S.54°W., 169.6 ft. scribed ¼ S3 CS BT.
No trees near to North.

Coos County Surveyors Office - Michael Dado, Surveyor - Crew: Matthew Martin & Bill Hales - 01/20/2015 - C.S. File 65/87-23

Condition report only
We find a 2½" brass cap on a 1¼" iron pipe, 0.8' tall, in good condition and solid in a mound of rocks per Byron. 1963
 W.Cedar post 2' North of BCIP
 31" D.Fir stump, N.09°30'W., 18.34' cont. next pg

