

TOWNSHIP 29 RANGE 09 POINT IDENTIFIER # 500100

PRIMARY CORNER DESCRIPTION Sec. Cor. for 34 & 35; 2 & 3, T30-9

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by Dennis Hathorn, Deputy Surveyor under Contract #57, dated April 12, 1855 - (DCSO records Vol. 17 Page(s) 7374)

Set post cor. of secs. 2, 3, 34 and 35, from which
A Fir 8" dia., bears N.69°E., 6 lks. dist.
A Fir 6" dia., bears N.67°W., 8 lks. dist.
A Fir 15" dia., bears S.51°W., 7 lks. dist.
A Cedar 6" dia., bears S.54°E., 51 lks. dist.

Douglas Co. Surveyors Office - James Byron, Deputy - Milo Godfrey; C. Putnam, crew - Oct. 20, 1959 - C.S. 49/100-74

Found - Orig. 6" now 12" Cedar, rec. S.54°E., 33.7 ft. I find should be S.48°E., 22.7 ft., shows good scribing "3 9W S2"
Orig. 15" now 34" W.Fir S.51°W., 4.6 ft. I open and find good scribing "BT".
No trace of other BTs found.
Find scribed stake at corner.
Set brass cap alongside scribed stake, mkd.
County Surveyors Office
S34 | S35 T29S R9W
S 3 | S 2 T30S
1959

New BTs- 16" W.Fir bears N.11°E., 24.3 ft. scribed S35 T29S R9W CS BT.
11" Cedar bears N.40°W., 29.3 ft. scribed S34 T29S R9W CS BT.

BLM resurvey by John Jelley, Cadastral Surveyor, Group #'s 350 & 606, surveyed Aug/Oct. 1966 - (DCSO records Vol. 34 Page(s) 14027)

The Sec. Cor., perpetuated and recorded by Byron in 1959, monumented with an iron pipe 1" dia., firmly set, extending 14" above the ground with brass cap mkd. in 1959, from which the remaining original bearing trees:
A Cedar 15" dia., bears S.50°E., 34½ lks. dist., with scribe marks T30S R9W S2 BT visible on open blaze. (Rec. S.54°E., 51 lks.)
A W.Fir 32" dia., bears S.51°W., 7 lks. dist., with illegible scribe marks visible on opened blaze.
and bearing trees mkd. by Byron:
A W.Fir 17" dia., bears N.9°E., 38 lks. dist., with healed double blaze.
(Cont. Next Page)

TOWNSHIP 29 RANGE 09 POINT IDENTIFIER # 500100

PRIMARY CORNER DESCRIPTION Sec. Cor. for 34 & 35; 2 & 3, T30-9

| | |
|-------------|-------------------|
| Alias _____ | Description _____ |
| Alias _____ | Description _____ |
| Alias _____ | Description _____ |
| Alias _____ | Description _____ |

A Cedar 13" dia., bears N.40°W., 44 lks. dist., with scribe marks T29S R9W S34 CS BT visible on partly healed blaze.
Add marks BLM 1966 to brass cap.

BLM Dependent retracement by A Bert Skeesick Cadastral Surveyor, Group No. 2300 surveyed Oct. 2007 - (DCSO records 2010 plat & copy of map in Vol. 56 Page(s) 21925)

The cor. of secs. 2, 3, 34 and 35, monumented with an iron post, 1½" dia., firmly set, projecting 14" above the ground, with brass cap mkd. as reported in 1966, from which the remaining original bearing trees
A cedar, 24" dia., bears S.50°E., 22.8 ft. with a healed blaze.
A fir, 33" dia., bears S.51°W., 4.6 ft., with no marks visible on an opened blaze.
and the bearing trees mkd. by Byron, in 1959
A fir, 26" dia., bears N.9°E., 25.1 ft., with healed double blaze.
A cedar, 22" dia., bears N.40°W., 29.0 ft., with healed double blaze.

Ron Quimby - Crew: N. Fromdahl & R. Olsen - 4/2015 - C.S.
File 65/87-45

Condition report only
Found - DCSO brass cap.
25" W.Fir N.9°E., 25.1 ft. good scar.
24" Cedar S.50°E., 22.8 ft. good scar.
32" W.Fir S.51°W., 4.6 ft. good scar.
23" Cedar N.40°W., 29.0 ft. good scar.
Note - Hand held Lat & Long NAD 83
N 42°59.781
W 123°44.509