

PRIMARY CORNER DESCRIPTION Sec. Cor. for 14, 15, 22 and 23

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GL0 survey by Dennis Hathorn, Deputy Surveyor under Contract #57, dated April 12, 1855 - (DCSO records Vol. 16 Page(s) 6624)

Set post cor. secs. 14, 15, 22 and 23, from which

- A Fir 8" dia., bears N.5°E., 12 lks.
- A Fir 12" dia., bears S.6°W., 9 lks.
- A Laurel 5" dia., bears N.20°W., 6 lks.
- A Laurel 4" dia., bears S.24°E., 10 lks.

GL0 resurvey by William M. Porter, Deputy Surveyor, Under Special Instructions dated June 5, 1907, Independent of, but in connection with his contract #768, dated March 8, 1907 - (DCSO records Vol. 16 Page(s) 6638-39)

Intersect at cor. of secs. 14, 14, 22 and 23. Post badly decayed and two witness trees gone. Trees standing agree with notes furnished by the Surveyor General.

Set a Cedar post 3 ft. long, 4" sq., 24" in the ground and marked T29S S14 on NE.; R9W S23 on SE.; S22 on SW.; and S15 on NW. faces and 3 notches on S. and 2 notches on E. edges, in lieu of old post, and established witnesses for those destroyed.

- A Fir 9" dia., bears S.70°W., 38 lks. dist. mkd. T29S R9W S22 BT.
- A Fir 18" dia., bears N.65°W., 26 lks. mkd. T29S R9W S15 BT.

Douglas Co. Surveyors Office - James Byron, Deputy - Milo Godfrey; C. Putnam, crew - Sept. 1959 - C.S. File 49/100-53

Found - Fir now 24", had been opened previously and scribe marks "S R9W S15 BT" plainly visible. This tree bears N.65°W., 17.2 ft. from corner.

Old uprooted snag, 24" dia., S.6°W., 5.9 ft., chopped open and found portion of scribe marks illegible.

Rotted Fir snag 9" dia., S.70°E., 25.1 ft. (Porter calls for 8" Fir S.70°W., 25.1 ft., wrong quadrant?), showing scribe "T29S R9W S23 BT", face had never grown over.

No trace of any other BTs could be found.

Set Brass cap at cor. mkd: County Surveyors Office

T	29	S	R	9	W
	S	15		S	14
	S	22		S	23

1959

(Cont. Next Page)

PRIMARY CORNER DESCRIPTION Sec. Cor. for 14, 15, 22 and 23

Alias	Description
_____	_____
_____	_____
_____	_____
_____	_____

Blaze and scribe new trees:
18" D.Fir S.60°W., 26.5 ft. mkd. T29S R9W S22 CS BT
15" D.Fir N.2°E., 10,8 ft. mkd. T29S R9W S14 CS BT.
15" I.Cedar S.47°E., 43.2 ft. mkd. T29S R9W S23 CS
BT.

BLM resurvey by John Jelley, Cadastral Surveyor, Group #'s
350 & 606, surveyed Aug/Oct. 1966 - (DCS0 records Vol. 34
Page(s) 14021)

The Sec. Cor., perpetuated and recorded by Byron in 1959,
monumented with an iron pipe 1" dia., firmly set, extending
18" above the ground, with brass cap mkd. in 1959, from which
the remaining original bearing tree
A down Fir 24" dia., bears S.6°W., 9 lks. dist., with
illegible scribe marks visible on partly opened blaze.
and bearing trees mkd. by Porter in 1907
A rotted Fir stump 12" dia., bears S.70°E., 38 lks. dist.,
with scribe marks 23 BT visible on open blaze. (Rec.
S.70°W.)
A Fir 23" dia., bears N.65°W., 27 lks. dist., with scribe
marks S R9W S15 BT visible on open blaze. (Rec. 26
lks.)
and bearing trees mkd. by Byron
A Fir 16" dia., bears N.2°E., 16½ lks. dist., with scribe
marks T29S R9W S14 CS BT visible on partly healed
double blaze.
A Cedar 18" dia., bears S.47°E., 65 lks. dist., with
scribe marks T29S R9W S23 CS BT visible on partly
healed double blaze.
A Fir snag 18" dia., bears S.60°W., 40 lks. dist., with
scribe marks T29S R9W S22 CS BT available on double
blaze.
and a new bearing tree
A Cedar 13" dia., bears S.19°W., 30 lks. dist., mkd T29S
R9W S22 BT.
Add marks BLM 1966 to brass cap.

Ronald L. Rice, Ward NW - Jason Collver - March 20, 2012 -
C.S. File 65/76-34

Found - DCS0 2½" brass cap on iron pipe, dated 1959,. In
fence corner wired to corner post.
Rotted Fir stump 12" dia., bears S.70°E., 25.1 ft.
scribing visible
Rotted Fir stump 23" dia., bears N.65°W., 17.8 ft.
scribing visible
continued next page

