

TOWNSHIP 29 RANGE 09 POINT IDENTIFIER # 540300

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 23 and 26

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GL0 survey by Dennis Hathorn, Deputy Surveyor under Contract #57, dated April 12, 1855 - (DCSO records Vol. 16 Page(s) 6623)

Set ¼ sec. post, from which
A Fir 24" dia., bears N.79°W., 37 lks.
A Fir 12" dia., bears S.0°30'W., 49 lks.

J.W. Cole, Deputy Co. Surveyor - P.W. Wolford, crew - Sept. 1920 - Field Book 48 Pg. 10+; Vol. 3 Pgs. 70-71; C.S. File 6/17

Set from remains of original BTs. Set 1" x 30" Iron pipe from which
A Fir 50" dia., S.31½°W., 61.5 ft.
A Fir 36" dia., N.81°W., 50.0 ft.

Douglas Co. Surveyors Office - James Byron, Deputy - Milo Godfrey; C. Putnam, crew - Sept. 1959 - C.S. File 49/100-56

Found - 1" sq. shaft at corner.
60" Fir stump, S.31½°W., 61.5 ft., no scribing found, stump cut low.
Find root system of large Fir that checks bearing and distance for NW. BT.
I do not set brass cap at corner.
New BTs- 24" Fir bears S.29½°W., 147.0 ft. scribed ¼ S26 CS BT.
7" Fir bears N.27°W., 112.5 ft. scribed ¼ S23 CS BT.

BLM resurvey by John Jelley, Cadastral Surveyor, Group #'s 350 & 606, surveyed Aug/Oct. 1966 - (DCSO records Vol. 34 Page(s) 14018-19)

The ¼ sec. cor., perpetuated and recorded by Cole, in 1920, determined from an original bearing tree which is no longer in existence, monumented with an iron axle, 1" dia., firmly set, extending 8" above the ground, from which the remains of bearing trees mkd. by Cole:
A stump hole with Fir roots bears N.81°W., 76 lks. dist.
A sawed Fir stump 58" dia., bears S.31½°W., 93 lks. dist., no marks visible.
and bearing trees mkd. by Byron in 1959:
A Fir 9" dia., bears N.27°W., 170 lks. dist., with healed blaze.
A Fir 22" dia., bears S.29½°W., 222 lks. dist. with healed double blaze.

(Cont. Next Page)

TOWNSHIP 29 RANGE 09 POINT IDENTIFIER # 540300

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 23 and 26

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

At the corner point
Set an iron post, 28" long, 2 1/2" dia., 24" in the ground,
with brass cap mkd:

T 29 S R 9 W

¼ S 23

S 26

1966

Reset iron axle alongside the iron pipe.
Corner is located at the intersection of fences extending N.,
S., E., and W.

BLM resurvey by A. Bert Skeesick Cadastral Surveyor under
Group #2043, surveyed May/June 2003 - (DCSO rec. Vol. 55
Page(s) 21347-8)

The ¼ sec. cor. of secs. 23 & 26, monumented with an iron
post, 2½" dia., firmly set, projecting 8" above ground,
(alongside of which is an axle, 1" dia., firmly set,
projecting 4" above ground) with brass cap (properly) mkd.
from which the remains of a bearing tree mkd. by the Douglas
County Surveyor's Office in 1920, reported by Jelley

A sawed fir stump, 58" dia., bears S.31½°W., 61.4 ft.,
with no marks visible.

and the remains of bearing trees mkd. by the Douglas County
Surveyor's Office in 1959, reported by Jelley

A sawed fir stump, 34" dia., bears S.29½°W., 146.5 ft.
with a healed double blaze.

A fir, 13" dia., bears N.27°W., 112.2 ft., with a healed
blaze.

and a new bearing tree

A fir, 10" dia., bears S.27¼° W., 42.3 ft., mkd. ¼ S26 BT.
Each new bearing tree has a 2½"x¼" magnetic nail (Mag Nail)
driven at the base right side-center, unless otherwise
described in the corner description.