

TOWNSHIP 29 RANGE 09 POINT IDENTIFIER # 700140

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Sec. 36; & 31, T29-8

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

<p>GL0 survey by Dennis Hathorn, Deputy Surveyor under Contract #57, dated April 12, 1855 - (DCSO records Vol. 16 Page(s) 6575)</p> <p>-----</p> <p>Set ¼ sec. post, from which A Fir 36" dia., bears N.42°W., 9 lks. dist. A Fir 15" dia., bears S.33°E., 33 lks. dist.</p>
<p>G.G. Stewart - Wit: W.S. Crear; E.J. Kennedy - May 22, 1922 -Vol. 3 Page 121</p> <p>-----</p> <p>Renewed O.B.T.s marks. Set Iron pipe for corner.</p>
<p>Douglas Co. Surveyors Office - James Byron, Deputy - Milo Godfrey; S. Bilow, crew - July 17, 1958 - C.S. File 49/100-4</p> <p>-----</p> <p>Found - Fir stump, now 28" dia., S.33°E., 21.8 ft. Chopped out lower blaze and found "BT" scribed in wood. More recent bark scribing "¼ S BT" Fir stump, now 48" dia., N.42°W., 5.9 ft. Lower scar has been chopped into but not opened to original blaze.</p> <p>Set Brass cap at cor. mkd: County Surveyors Office T 29 S R9W S36 S31 R8W 1958</p> <p>New BTs- 12" W.Fir N.11°E., 32.3 ft. scribed ¼ S31 CS BT. 8" W.Fir S.28°W., 13.0 ft. scribed ¼ S36 CS BT.</p>
<p>Fd. and used in BLM resurvey by Donald Beck, Cadastral Surveyor, under Group #584 - Surveyed July 1965 - (DCSO records Vol. 33 Page(s) 13881)</p> <p>-----</p> <p>Add the marks BLM 1965 to top of brass cap.</p>
<p>Fd. and used in BLM resurvey by Wayne L. Rogers, Cadastral Surveyor and Robert H. Browning, Surveying Technician, under Group #1583 - Surveyed April/June 1991 - (DCSO records Vol. 49 Page(s) 18670-71)</p>
<p>Fd. OK, Feb. 1997 by D. Bentz - M 126-39</p>
<p>1</p>