

TOWNSHIP 29½ RANGE 07 POINT IDENTIFIER # 140100

PRIMARY CORNER DESCRIPTION 1/4 Cor. Sec 31; & Sec 6, T30-7

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Original - William H. Byars, Deputy Surveyor, Under Contract No. 456, dated July 28, 1882 (DCS0 records Vol. 15 Page(s) 6553-54

Set a Fir post, 4' long, 4" sq., 20" in ground, for the ¼ sec. cor. mkd. ¼ S. on the North face, and from which,
A Fir, 12" dia., bears N.25°E., 29 lks. mkd. ¼ S. BT.
A Chinquapin, 12" dia., bears S.15°E., 36 lks. mkd. ¼ S. BT.

Re-establishment of corners - Fred Mensch, U.S. Deputy Surveyor - under date of April 18, 1924 (DCS0 Vol. 14 Page 6048)

Intersect the point for ¼ sec. cor. located by measurement from the orig. bearing trees.
At the exact cor. point
Set an iron post, 3' long 1" dia., 28" in the ground, for ¼ sec. cor. with brass cap mkd:
$$\frac{1}{4} \begin{array}{l} S31 \\ T29\frac{1}{2} \\ S6 \end{array}$$

from which (the orig. BTs)
A Chinquapin, 14" dia., bears S.15°E., 36 lks. mkd. ¼ S BT.
A Fir, stump, bears N.33°E., 29 lks. (not N.25°E.), blazes show on the stump.
New bearing trees:
A Fir, 22" dia., bears N.4°W., 33 lks. mkd: ¼ S31 T29½ BT.

Douglas Co. Surveyors Office - James W. Byron, Deputy & Crew June 1962 - C.S. 49/139-82

Found - Brass cap set in 1924 & BTs as follows:
14" Chinquapin, S.15°E., 27.8' (windfall)
22" Fir, N.4°W., 21.8' (stump)
Both show good scars.
New BTs- 17" W. Fir, S.32°E., 32.6' scribed ¼ S6 CS BT.
7" Chinquapin, N.34°W., 11.3' scribed ¼ S31 CS BT.

Douglas Co. Surveyors Office - Randall Smith, Deputy - Stephen Flaue - Dec. 20, 1991 - C.S. File 64/21-15

Found - 2½" dia., 1924 GL0 brass cap on a 1" O.D. Iron pipe, protrudes 6" above ground.
(Cont. Next Page)

Alias	Description
_____	_____
_____	_____
_____	_____
_____	_____

12" down and rotted 14" Chinquapin, root hole bears S.15°E., 27.8' (agrees with record) Orig. BT.
 22" now 20" dia., 1½' high rotted D. Fir stump, with a rotted blaze, bears N.4°W., 21.8' (agrees w/ Rec.) 1924 BT.
 17" now 21" dia., W. Fir, with a partially healed double blaze illegible scribing visible, bears S.32°E., 36.2' (Rec. S.32°E., 32.6' error in rec.?) Byron's 1962 renewal.
 7" now 10" dead Chinquapin with a fully healed double blaze, bears N.34°W., 11.3' (agrees with rec.) Byron's 1962 renewal.
 6" dia., D. Fir, with a partially healed pitched over blaze, bears N.68°E., 11.3' (tag reads N.68°E., 12.0' dist. to center of trunk) Unrecorded 1988 BLM tree.
 New BTs- 18" R. Cedar double blazed and scribed "¼ S31 CS BT" bears N.62½°W., 17.6'.
 6" D. Fir double blazed and scribed "¼ S6 CS BT" bears S.40°W., 17.0'.

BLM resurvey Wayne L. Rogers, Dale T. Bedell, & Boyd W. Peterson, Cadastral Surveyors, under special instructions dated August 8, 1988, Group No. 1456, surveyed Sept. 6, 1988/Feb. 28, 1989. (DCSO records Vol. 50 Page(s) 19027-28)

The ¼ sec. cor. of Secs. 6 and 31, monumented with an iron post, 1 in. diam., firmly set, projecting 6 ins. above ground, with brass cap mkd:

T 29½ S
 ¼ $\frac{S\ 31}{S\ 6}$
 1924

from which the remains of an original bearing tree
 A root hole, bears S. 15° E., 36 lks. dist., with a down and rotted chinquapin alongside, 17 ins. diam., no remaining marks.
 and the remains of a bearing tree mkd. by Mensch
 A rotted fir stump, 20 ins. diam., bears N. 4° W., 33 lks. dist., no remaining marks.
 and the remains of bearing trees mkd. by James W. Byron, Deputy County Surveyor, in 1962
 A chinquapin snag, 10 ins. diam., bears N. 34° W., 17 lks. dist., with healed blaze.
 A fir, 22" diam., S.32°E., 55 lks. with fragmentary scribe marks on partially healed blaze.
 and a new bearing tree
 A fir, 6" diam., bears N.68°E., 18 lks. mkd. ¼ S31 BT.

TOWNSHIP 29½ RANGE 07 POINT IDENTIFIER # 140100

PRIMARY CORNER DESCRIPTION 1/4 Cor. Sec. 31 (& S. 6 of T30-7)

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

BLM Resurvey by Wayne L. Rogers; Dale T. Bedell; Boyd W. Peterson; Cadastral Surveyors - Under Group #1466, Surveyed Sept. 1988/Feb. 1989 - (DCSO records Vol. 50 Page(s) 19027-28)

The ¼ sec.cor., monumented with an iron post, 1" dia., firmly set, projecting 6" above ground, with 1924 BLM brass cap, from which the remains of an original bearing tree

A root hole bears S.15°E., 36 lks. dist. with a down and rotted chinquapin alongside, 17" dia., no remaining marks.

and the remains of a bearing tree mkd. by Mensch

A rotted Fir stump 20" dia., bears N.4°W., 33 lks. dist., no remaining marks.

and the remains of bearing trees mkd. by Byron in 1962

A Chinquapin snag 10" dia., bears N.34°W., 17 lks. dist. with healed blaze.

A Fir 22" dia., bears S.32°E., 55 lks. dist. with fragmentary scribe marks on partially healed blaze.

and a new bearing tree

A Fir 6" dia., bears N.68°E., 18 lks. dist. mkd. ¼ S31 BT.