

TOWNSHIP 29½ RANGE 07 POINT IDENTIFIER # 240200

PRIMARY CORNER DESCRIPTION N 1/4 Cor. Sec. 32 Only

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Orig. (Corrective resurvey)- Fred Mensch, U.S. Deputy Surveyor - under date of April 18, 1924 (DCSO Vol. 14 Page 6040)

Set an iron post, 3' long, 1" dia., 28" in the ground, for ¼ sec. cor. 32 only, T29½S R7W, with brass cap mkd:

¼S32
T29½
1924

from which,

A Fir, 18" dia., bears S.41°E., 22 lks. mkd. ¼ S32 T29½ BT
A Fir, 10" dia., bears S.52°W., 30 lks. mkd. ¼ S32 T29½ BT

Douglas Co. Surveyors Office - Ben B. Irving, Co. Surveyor - James Byron - Ray Irving - Work done on order from County Court in connection with Co. Rd. #38 - Feb. 1954 - C.S. File 46/36

Found - Brass cap at corner.
18" Red Fir, S.41°E., 22 lks., stump only left.
New BTs- 10" W. Fir, S.0°30'E., 90.0' mkd: T29½S R7W ¼ S32 CS BT.
10" R. Fir, N.83°E., 93.4' mkd: T29½S R7W ¼ S32 CS BT.

Douglas Co. Surveyors Office - James W. Byron, Deputy & Crew - June 1962 - C.S. File 49/139-80

Found - Brass cap set in 1924 & BTs as follows:
14" W. Fir, S.0°30'E., 90.0'
10" R. Fir (snag) N.83°E., 93.4'
New BT - 7" Cedar S.53°E., 42.2' scribed N ¼ S32 CS BT.

BLM resurvey, by Boyd W. Peterson, under special instructions dated August 8, 1988., under Group #1456 Surveyed Sept./Dec. 1988 (DCSO records Vol. 49 Page 18815)

The ¼ sec. cor. of sec. 32 only, T29½S R7W, perpetuated and recorded by Irving in 1954 and further perpetuated and recorded by Byron in 1962; monumented with an iron post, 1" dia., firmly set, projecting 6" above ground, with brass cap mkd:

¼ S32
T29½S
1924

from which the remains of the orig. bearing trees:
(Cont. Next Page)

TOWNSHIP 29½ RANGE 07 POINT IDENTIFIER # 240200

PRIMARY CORNER DESCRIPTION N 1/4 Cor. Sec. 32 Only

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

A sawed Fir stump, 19" dia., bears S.41°E., 22 lks., with healed blaze.
A sawed Fir stump, 10" dia., bears S.52°W., 30 lks., no marks visible on partially healed blaze.
and the remains of a bearing tree mkd. by Irving
A Fir snag, 26" dia., bears South, 136 lks., with healed double blaze.
and the remains of a bearing tree mkd. by Byron
A broken top cedar, 16" dia., bears S.53°E., 64 lks., with healed double blaze.
and new bearing trees
A Fir, 10" dia., bears S.25°E., 19 lks., mkd: ¼ S32 BT.
A Cedar, 14" dia., bears S.6°W., 20 lks., mkd: ¼ S32 BT.