

TOWNSHIP 29½ RANGE 07 POINT IDENTIFIER # 300100

PRIMARY CORNER DESCRIPTION Sec Cor for 32, 33; & 4 & 5 T30-7

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Original - William H. Byars, Deputy Surveyor, Under Contract No. 456, dated July 28, 1882 (DCSO records Vol. 15 Pages 6551-52)

-----  
Set a stone, 14x12x6 ins. 10" in ground, for the cor. to secs. 4, 5, 32 & 33, mkd. with 4 notches on the East and 2 notches on the West angles of the same and from which,  
A Cedar, 18" dia., bears N.54°E., 15 lks. Mkd: T29S R7W S33 BT.  
A Laurel, 15" dia., bears S.20°E., 32 lks. Mkd: T30S R7W S4 BT.  
A Pine, 44" dia., bears S.42°W., 138 lks. Mkd: T30S R7W S5 BT.  
A Pine, 44" dia., bears N.72°W., 106 lks. Mkd: T29S R7W S32 BT.

W.F. Briggs, 1897 - Field Book 2 Pg. 25  
Laurel 12", S.20½°E., 29 lks.  
Pine 36", N.72½°W., 140 lks.  
Pine 40", S.41½°W, 105 lks.  
Cedar 12", N.45°E., 16 lks.

Re-establishment of corners - Fred Mensch, U.S. Deputy Surveyor - under date of April 18, 1924 (DCSO Vol 14 Pg 6050)

-----  
Intersect the cor. of secs. 4, 5, 32, & 33, which is a sandstone, 8x12x6 ins. above ground, firmly set, mkd. with 4 notches on E. and 2 notches on W. edges; from which the orig. bearing trees:  
A Cedar, 30" dia., bears N.54°W., 15 lks. I re-mark T29½S R7W S33 BT.  
A Laurel, 24" dia., bears S.15°E., 32 lks., (not S.20°E.)  
A Cedar, rotted down, bears S.48°W., 138 lks., (not a pine bearing S.42°W.)  
A Pine (dead), 50" dia., bears N.72°W., 106 lks.  
New bearing trees:  
A Pine, 10" dia, S.36°W., 45 lks., mkd: T30S R7W S5 BT.  
A Pine, 14" dia., bears N.20°W., 81 lks., mkd: T29½S R7W S32 BT.  
This cor. is on top of spur, slopes S.20°W.

Douglas Co. Surveyors Office - James W. Byron, Deputy & Crew - June 1962 - C.S. File 49/139

-----  
Found - All 4 1924 BTs.  
NE BT now down, Corner stone not found.  
(Cont. Next Page)

TOWNSHIP 29½ RANGE 07 POINT IDENTIFIER # 300100

PRIMARY CORNER DESCRIPTION Sec. Cor. 32, 33; & 4, 5, T30-7

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Set - PK nail & chiseled 3" + on exposed flat sandstone rock. We also chiseled CS in rock near cross.  
New BT - 19" Fir, bears N.65°E., 21.7' scribed S33 T29½S R7W CS BT.

Howard Johnstone - For: Roseburg Lumber Co. - June 29, 1984 - M 97-14

-----

Found - PK nail hole in sandstone scribed "CS +"  
18" Cedar, N.71°E., 8.3' (N.54°E., 9.9') down - scribe visible.  
21" Fir, N.65°E., 21.7', healed.  
36" Madrone, S.15°E., 21.1', rotted face.  
20" Pine, S.36°W., 29.7', healed.  
17" Pine, N.20°W., 53.5', healed.

Set - 2" brass tablet in concrete grout at PK nail location. Tablet marked with "LS 498".

FD OK by - BLM resurvey, by Boyd W. Peterson, under special instructions dated August 8, 1988. Under Group #1456 Surveyed Sept./Dec. 1988 (DCSO records Vol. 49 Page(s) 18818-19)