

TOWNSHIP 29½ RANGE 07 POINT IDENTIFIER # 340200

PRIMARY CORNER DESCRIPTION North 1/4 Cor. Sec. 33 only

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Orig. (Corrective resurvey)- Fred Mensch, US Deputy Surveyor
- under date of April 18, 1924 (DCSO Vol. 14 Pgs 6041-42)

Point for ¼ sec. cor. of sec. 33 T29½S T7W, later determined.
Set an iron post, 3' long, 1" dia., 28" in the ground, for ¼
sec. cor. of sec. 33, T29½S R7W, with brass cap mkd:

¼ S33
T29½
1924

from which

A Fir, 6" dia., S.84°E., 12 lks., mkd: ¼ S 33 T29½ BT.
A Fir, 9" dia., S.58°W., 20 lks., mkd: ¼ S 33 T29½ BT.

Douglas Co. Surveyors Office - James W. Byron, Deputy - Dale
McFarland - John Powell - June 1962 - C.S. File 49/139-79

Found - Brass Cap set in 1924.
SE BT is rotted stump, scribing (¼S 33 T29½ BT)
visible.
SW BT down, shows good scar.
New BTs- 11" Fir, S.42°W., 28.5' scribed N¼ S33 CS BT.
8" Cedar, S.28°E., 48.4' scribed N¼ S33 CS BT.

BLM resurvey by Harvey Wofford, G. Steven Popken, & James J.
Carlson, instructions dated August 29, 1974 under Group #851.
Surveyed Sept. 1974/May 1976 (DCSO records Vol. 39 Page
15815-16)

The ¼ sec. cor. of sec. 33 only, on the N. bdy of T29½S R7W,
monumented with an iron post, 1" dia., firmly set, projecting
6" above ground, with brass cap mkd:

¼ S33
T29½
1924

from which the remains of the orig. bearing trees

A decayed Fir stump, 6" dia., bears S.84°E., 12 lks., with
scribe marks ¼ S33 T29½ BT visible on open blaze.

A root hole, bears S.58°W., 20 lks., with a down fir
alongside, 10" dia., with healed blaze.

and bearing trees mkd. by Bryon in 1962

A Cedar, 12" dia., bears S.28°E., 73½ lks., with scribe
marks 4 S33 CS visible on partially healed blaze.

A Fir, 16" dia., bears S.42°W., 44 lks., with healed
blaze.