

TOWNSHIP 29½ RANGE 07 POINT IDENTIFIER # 500100

PRIMARY CORNER DESCRIPTION SE Cor Sec 34 (SW cor S 35, T29-7)

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO Survey - W.H. Byars - contract #152 dated June 3, 1871
(DCSO records Vol. 17 Pg. 7232)

Set post cor. to secs. 2, 3, 34, & 35 from which
A Laurel, 5" diam., bears N.40°E., 8 lks.
A Laurel, 6" diam., bears S.75°E., 6 lks.
A Laurel, 6" diam., bears S.10°W., 18 lks.
A Laurel, 8" diam., bears N.60°W., 17 lks.

GLO Resurvey - William H. Byars, Deputy Surveyor, Under
Contract No. 456, dated July 28, 1882 (DCSO records Vol. 15
Page(s) 6549)

At the cor., which is a post, 4" square, firmly set in the
ground and mkd. T29S., S35 on NE. face, and R7W S2 on the SE.
face, T30S S3 on the SW. face & S34 on the NW. face; also 2
notches on the East angles, and 4 notches on the West, and
from which,
A Laurel, 5" diam., bears N.40°E., 8 lks., mkd. T29S R7W
S35 BT.
A Laurel, 6" diam., bears S.75°E., 6 lks., mkd. T30S R7W
S 2 BT.
A Laurel, 6" diam., bears S.10°W., 18 lks., mkd. T30S R7W
S3 BT.
A Laurel, 8" diam., bears N.60°W., 17 lks., mkd. T29S R7W
S34 BT.

GLO Re-establishment of corners - Fred Mensch, U.S. Deputy
Surveyor - under date of April 18, 1924 (DCSO Vol. 14 Page
5978-79)

Intersect the Byar's N. bdy. of T30S R7W, 76 lks.. W. of the
Byars' cor. of secs. 2, 3, 34, & 35 which is a fir post, 6"
sq., 12" above ground properly marked; the bearing trees have
all rotted down, but on the NW. and SE. logs dim marks can be
found.

Along the W. side of the post

Set an iron post, 3 ft. long, 3" diam., 27" in the ground,
for SE. cor. of T29½S R7W and cor. of secs. 2, 3, 34, &
35, with brass cap marked:

T29½S	T29S
R7W	R7W
S34	S35
<hr/>	
S3	S2
T30S	R7W
1924	

(Cont. Next Page)

TOWNSHIP 29½ RANGE 07 POINT IDENTIFIER # 500100

PRIMARY CORNER DESCRIPTION SE Cor Sec 34 (SW cor Sec 35, T29-7)

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

from which
A fir, 16" diam., bears N.52°E., 68 lks., mkd. T29S R7W S35 BT.
A fir, 14" diam., bears S.75°E., 44 lks., mkd. T30S R7W S2 BT.
A cedar, 8" diam., bears S.26°W., 21 lks., mkd. T30S R7W S3 BT.
A fir, 30" diam., bears N.29°W., 83 lks., mkd. T29½S R7W 34 BT.

James W. Byron, Dep. Co. Surveyor - John Powell & Dale McFarland - May/June 1962 - C.S. 49/139-86

Found - Brass cap at corner & all BT's except NE. BT.
New BT- 6" R. Fir, bears N.39°E., 25 ft., scribed S35 CS BT.

BLM resurvey by Harvey Wofford, G. Steven Popken, & James J. Carlson, instructions dated August 29, 1974 under Group #851. Surveyed Sept. 1974/May 1976 (DCSO records Vol. 39 Page 15817-18)

From the corner, monumented with an iron post, 3" diam., firmly set projecting 15" above ground, with brass cap mkd.
T29½S | T29S
R7W |
S34 | S35

S 3 | S 2
T30S | R7W
1924

from which the remains of bearing trees mkd. by Mensch
A fir, 25" diam., bears N.54°E., 68 lks., with healed double blaze.
A root hole, bears S.75°E., 42 lks., with a down fir alongside, 15" diam., with healed double blaze. (Record, 44 lks.)
A cedar snag, 9" diam., bears S.26°W., 21 lks., with scribe mks. R7W visible on open double blaze.
A fir, 38" diam., bears N.27½°W., 86 lks., with healed double blaze. (Record, N.29°W., 83 lks.)
and the remains of a bearing tree mkd. by the Co. Surveyor in 1962
A fir snag, 8" diam., bears N.34°E., 38 lks., with scribe mks S35 CS BT visible on open double blaze.
and new bearing trees
A fir, 13" diam., bears S.54°E., 69½ lks., mkd. T30S R7W S2 BT.
A fir, 8" diam., S.36°W., 39½ lks. mkd. T30S R7W S3 BT

TOWNSHIP 29½ RANGE 07 POINT IDENTIFIER # 500100

PRIMARY CORNER DESCRIPTION SF Cor Sec 34 (SF Cor Sec 35, T29-7)

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Fd. Ok. - Howard Johnstone - Jan. 30, 1981 - M 86-77

Douglas Co. Surveyors office - Randall Smith & Stephen Flause
- Dec. 19, 1991 - C.S. 64/21-14

Found - A 3½" diam. 1924 GLO brass cap on a 3" O.D. Iron pipe protruding 14" above ground.
16" now 27" diam., D. Fir with a fully healed double blaze, bears N.52½°E., 44.9 ft. (Rec. N.54°E., 44.9 ft) 1924 GLO.
1924 GLO S.75°E., 27.7 ft. BT is gone.
8" now 11" diam., 2 ft. high Cedar stump, tree is down alongside stump, scribing visible "R7" bears S.26°W., 13.9 ft. (agrees with rec.) 1924 BT.
30" now 36" diam., D. Fir with a fully healed double blaze, bears N.27½°W., 56.8 ft. (agrees with rec.) 1924 BT.
6" now down and rotting 6" D. Fir with illegible scribing visible, bears N.34°E., 25.1 ft. (agrees with rec.) Byron.
13" now 12" diam., 7 ft. high D. Fir stump with a fully healed single blaze, bears S.51°E., 13.9 ft. (rec. S.54°E., 45.9 ft.) (tagged by B. Moyer in 1958, tag reads N.24½°E., 21 lks.) unsure of reason for bad brg's and dist. 1924 GLO.
8" now 13" diam. W. Fir with a fully healed single blaze bears S.36°W., 25.5 ft. (rec. S.36°W., 26.1 ft., to center of trunks) 1964 BT.
New BT - 8" D. Fir double blazed and scribed "T29S R7W S35 CS BT" bears N.43°E., 8.4 ft.
corner lies at the intersection of a south and east running cut lines, clear cut to the southeast. Approx. 125 ft. north of a gravel road.