

TOWNSHIP 30 RANGE 01E POINT IDENTIFIER # 241700

PRIMARY CORNER DESCRIPTION 1/4 Cor. Sec. 32 (South) T29-01E

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by Fred Mensch, US Deputy Surveyor, under contract No 797, dated April 19, 1910 - (DCSO records Vol 25 Pg 10570 & Vol. 26 Pg 10968)

A fir 20" dia., for 1/4 sec. cor. I mark 1/4 S 32 on N & 5 on S side, from which
A fir, 20" dia., bears N.33°W., 4 lks., mkd: 1/4 S32 BT.
A fir, 15" dia., bears S.28°E., 43 lks., mkd: 1/4 S5 BT.

GLO survey by Fred Mensch, Cadastral Engineer, under special instructions Dated June 7, 1922 - (DCSO records Vol. 25 Pages 10682-3 & Vol. 26 Page(s) 10985-6)

The 1/4 sec. cor. established for secs. 5 & 32 which is a fir, 20" dia., marked 1/4 S32 on N, & S5 on S side.
Hereafter this cor. will refer to sec. 32 only. I obliterate the marks on the S side of the cor. tree from which
A fir, 6" dia., bears N.40°E., 9 lks., mkd: 1/4 S32 BT, New BT
A fir, 20" dia., bears N.33°W., 4 lks., mkd: 1/4 S32 BT, Old BT.
I obliterate the marks on the old BT in sec. 5.

Douglas Co. Surveyors Office - M. Lenora Lading - Karen Cheney - Sept. 28, 1976 - C.S. File 59/24-21

Found - Orig. Corner tree (call 20" Fir) which is now a 24" rotten stump 6" above ground. From which:
An orig. 20" now 30" Fir, bears N.33°W., 2.6 ft. Tree is alive with well healed blaze.
An orig. 15" now 30" Fir, bears S.28°E., 28.4 ft. Tree is alive with well healed blaze.
Set - At true corner point:
A 1" x 36" I. Pipe with brass cap stamped:
Douglas Co. Surveyor
T29S
1/4 S 32 R
T30S 1
1976 E

Note - I. Pipe was pounded into heart of orig. corner tree.