

TOWNSHIP 30 RANGE 01E POINT IDENTIFIER # 640700

PRIMARY CORNER DESCRIPTION North 1/4 Cor. Sec. 1 only

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO resurvey by Norman D. Price, Cadastral Engineer, Leonard Carter, Public Land Surveyor, and George F. Dawson Jr., Transitman, under Group No. 175 surveyed April/Aug. 1937 - (DCSO records Vol. 34 Page(s) 14103)

-----  
From the ¼ sec. cor. of sec. 36 only on S bdy. of T29S R1E S.89°51'E 1.30 chs.  
A point 40.00 chs. in departure from the closing cor. of secs. 1 & 2  
Set an iron post, 3 ft long, 1" dia., 27" in the ground, for ¼ sec. cor. of sec. 1 only, with brass cap marked:

¼ S 1  
1937

from which

A W.Fir, 25" dia., bears S.39°E., 53 lks., mkd: ¼ S1 BT.  
A Yew, 4" dia., bears S.35°W., 28 lks., mkd: ¼ S1 BT.

-----  
Dennis Gaylord, USFS & Deputy Co. Surveyor - Witness: Walter Barton - March 3, 1977 - C.S. File 59/31-4

-----  
Found - 2½" Brass cap on 1" IP mkd. US GLO ¼ S1 1937. Township & range not shown on brass cap. Pipe bent over & buried 1 ft. deep I reference location of pipe, remove, straighten & replace in exact same location.  
A 32" D.Fir bears S.39°E., 34.98 ft. Has a healed blaze.  
BT to SW is gone. Placed County BT sign on Fir.  
New BT - A 8" Yew bears S.65°30'E., 78.4 ft. Scribed "¼ S1 CS BT" on a double blaze. Placed County BT sign on Yew.  
Note - Corner lies 200 ft. more or less south of Forest Service R. #293 & 25 ft. more or less north of the North bank of Jackson Creek.