

TOWNSHIP 30 RANGE 01 POINT IDENTIFIER # 300240

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 28 & 29

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by Dennis Hathorn, US Deputy Surveyor under contract 73 dated June 8, 1857 - (DCSO Records Vol 16 Pg 6661  
-----

A fir 4" dia., ¼ sec. corner, from which  
A fir, 6" dia., bears S.55°W. 25 lks.  
A fir, 6" dia., bears S.20°E. 15 lks.

WF Briggs - March 12, 1889 - Vol. 1 Page 130  
-----

Old BT down marked new BT  
Fir 4" S.50°W., 5 links  
Fir 6" S.70°E., 12 links.

Douglas Co. Surveyors Office - John M. Powell - 1/3/1968 - C.S. File 54/59  
-----

Not found  
No BTS. Old fence cor. at this location.

Bruce Shaner, PLS 430 - For: USFS - Jan. 1981 - RM 3-43  
-----

Set - Brass cap mkd: "T30S R1W WM ¼ S28 S29 RLS 430 1981"  
12" D.Fir BT, scribed "¼ S28 BT" bears N.34°E., 19.0 ft  
10" D.Fir BT, scribed "¼ S29 BT" bears N.38½°W., 30.6

David Edwards - For: Ireland & Sierra Pacific Industries - 3/2023 - M181-80  
-----

Found - Brass cap and IP  
16" dia. Fir bears N.34°E., 19.0'  
12" dia. Fir bears N.38½°W., 30.6'  
Both with healed blaze  
New - A 5.5' steel post is set 2' north.